

October 9, 2018

Carmi Strom Principal Webster Elementary 4801 Elm St. San Diego, CA 92102

Subject: Webster Elementary Drinking Water Project Closeout

#### Dear Carmi Strom:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Webster Elementary campus.

As part of a district wide effort initiated last year the Safety Office began testing all drinking water outlets at Webster Elementary for elevated levels of lead. Safety Office staff first identified all drinking water outlets and tagged them with a blue sticker. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to an accredited local laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Webster Elementary campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto Manager, Facilities Planning



Facility: Webster Elementary

**Report Type: Close Out Report** 

**Date of Report:** 10/9/2018

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
	2 Admin/Supply - Webster_01-02 Nurse Health - HLC1, West Wall	DWO-289-001	Faucet	<5	INIT	
2	1 Auditorium/Kitchen - Webster_01-01 Building Exterior, SW Corner of Lunch Court Lt Side	DWO-289-002	Drinking Fountain Bubbler	6.03	PLMB	4.16
3	Auditorium/Kitchen - Webster_01-01     Building Exterior, SW Corner of Lunch Court Middle	DWO-289-003	Drinking Fountain Bubbler	7.14	PLMB	3.70
4	Auditorium/Kitchen - Webster_01-01     Building Exterior, SW Corner of Lunch Court Rt Side	DWO-289-004	Drinking Fountain Bubbler	2.76	INIT	
5	1 Auditorium/Kitchen - Webster_01-01 Food Services/Kitchen - FSK1, South Wall	DWO-289-005	Faucet	4.81	INIT	
6	3 Classrooms 1-5 - Webster_01-03 Classroom - 01, North Wall	DWO-289-006	Drinking Fountain Bubbler	2.69	INIT	
7	3 Classrooms 1-5 - Webster_01-03 Classroom - 02, North Wall	DWO-289-007	Drinking Fountain Bubbler	1.67	INIT	
8	3 Classrooms 1-5 - Webster_01-03 Classroom - 03, North Wall	DWO-289-008	Drinking Fountain Bubbler	3.79	INIT	
9	3 Classrooms 1-5 - Webster_01-03 Classroom - 04, North Wall	DWO-289-009	Drinking Fountain Bubbler	3.94	INIT	
10	3 Classrooms 1-5 - Webster_01-03 Classroom - 05, North Wall	DWO-289-010	Drinking Fountain Bubbler	NA	INIT	
11	4 Classrooms 6-9 - Webster_01-04 Building Exterior, West Wall Lt Side	DWO-289-011	Drinking Fountain Bubbler	3.96	INIT	
12	4 Classrooms 6-9 - Webster_01-04 Building Exterior, West Wall Middle	DWO-289-012	Drinking Fountain Bubbler	11.34	PLMB	ND
13	4 Classrooms 6-9 - Webster_01-04 Building Exterior, West Wall Rt Side	DWO-289-013	Drinking Fountain Bubbler	<5	INIT	
14	4 Classrooms 6-9 - Webster_01-04 Classroom - 06, North Wall	DWO-289-014	Drinking Fountain Bubbler	17.70	PLMB	2.90
15	4 Classrooms 6-9 - Webster_01-04 Classroom - 07, North Wall	DWO-289-015	Drinking Fountain Bubbler	3.72	INIT	
16	4 Classrooms 6-9 - Webster_01-04 Classroom - 08, North Wall	DWO-289-016	Drinking Fountain Bubbler	2.09	INIT	
17	4 Classrooms 6-9 - Webster_01-04 Classroom - 09, North Wall	DWO-289-017	Drinking Fountain Bubbler	4.83	INIT	



**Facility: Webster Elementary** 

**Report Type: Close Out Report** 

**Date of Report:** 10/9/2018

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
18	Portable B01 - Webster Classroom - B01, East Wall	DWO-289-018	Drinking Fountain Bubbler	6.84	PLMB	1.50
	Portable B02 - Webster Classroom - B02, East Wall	DWO-289-019	Drinking Fountain Bubbler	8.66	PLMB	1.30
~~	Portable B03 - Webster Classroom - B03, East Wall	DWO-289-020	Drinking Fountain Bubbler	4.43	INIT	
21	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-021	Drinking Fountain Bubbler	5.09	FLTR	ND
22	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-022	Drinking Fountain Bubbler	2.40	INIT	
23	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-023	Drinking Fountain Bubbler	3.56	INIT	
24	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-024	Drinking Fountain Bubbler	3.27	INIT	
25	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-025	Drinking Fountain Bubbler	6.02	FLTR	ND
26	Portable Restrooms - Webster Building Exterior, East Wall	DWO-289-026	Drinking Fountain Bubbler	3.12	INIT	
27	Portable B05 - Webster Classroom - B05, West Wall	DWO-289-027	Drinking Fountain Bubbler	15.00	FLTR	0.91
28	Portable B04 - Webster Classroom - B04, West Wall	DWO-289-028	Drinking Fountain Bubbler	7.12	PLMB	1.20
29	Portable B06 - Webster Classroom - B06, East Wall	DWO-289-029	Drinking Fountain Bubbler	7.57	FLTR	ND
30	Portable B07 - Webster Classroom - B07, East Wall	DWO-289-030	Drinking Fountain Bubbler	26.10	FLTR	4.80
31	Portable B08 - Webster Classroom - B08, East Wall	DWO-289-031	Drinking Fountain Bubbler	11.80	PLMB	0.77
32	Portable B09 - Webster Classroom - B09, West Wall	DWO-289-032	Drinking Fountain Bubbler	9.31	FLTR	ND
33	Portable B10 - Webster Classroom - B10, West Wall	DWO-289-033	Drinking Fountain Bubbler	5.72	PLMB	4.60
	Portable B11 - Holly Drive Leadership Academy Classroom - B11, West Wall	DWO-289-034	Drinking Fountain Bubbler	1.30	INIT	



**Facility: Webster Elementary** 

**Report Type: Close Out Report** 

**Date of Report:** 10/9/2018

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
35	5 Kinder Rms 10-11 - Webster_01-05 Building Exterior, South Wall Lt Side	DWO-289-035	Drinking Fountain Bubbler	2.75	INIT	
36	5 Kinder Rms 10-11 - Webster_01-05 Building Exterior, South Wall Rt Side	DWO-289-036	Drinking Fountain Bubbler	1.94	INIT	
	5 Kinder Rms 10-11 - Webster_01-05 Kinder Classroom - 10, North Side of Island	DWO-289-037	Drinking Fountain Bubbler	3.63	INIT	
38	5 Kinder Rms 10-11 - Webster_01-05 Kinder Classroom - 11, North Side of Island	DWO-289-038	Drinking Fountain Bubbler	3.13	INIT	
39	Portable B14 - Holly Drive Leadership Academy Classroom - B14, West Wall	DWO-289-039	Drinking Fountain Bubbler	NA	INIT	
40	Portable B15 - Holly Drive Leadership Academy Classroom - B15, West Wall	DWO-289-040	Drinking Fountain Bubbler	NA	INIT	
41	6 Library - Webster_02-06 Faculty Workroom - WRK1, North Wall	DWO-289-041	Faucet	4.73	INIT	
42	6 Library - Webster_02-06 Building Exterior, West Wall Lt Side	DWO-289-042	Drinking Fountain Bubbler	1.38	INIT	
	6 Library - Webster_02-06 Building Exterior, West Wall Rt Side	DWO-289-043	Drinking Fountain Bubbler	<5	INIT	
44	7 Classrooms 12-21 - Webster_02-07 Classroom - 16, East Wall	DWO-289-044	Drinking Fountain Bubbler	0.92	INIT	
45	7 Classrooms 12-21 - Webster_02-07 Classroom - 15, South Wall	DWO-289-045	Drinking Fountain Bubbler	1.72	INIT	
46	7 Classrooms 12-21 - Webster_02-07 Classroom - 13, West Wall	DWO-289-046	Drinking Fountain Bubbler	4.74	INIT	
47	7 Classrooms 12-21 - Webster_02-07 Classroom - 12, West Wall	DWO-289-047	Drinking Fountain Bubbler	0.84	INIT	
48	7 Classrooms 12-21 - Webster_02-07 Classroom - 17, West Wall	DWO-289-048	Drinking Fountain Bubbler	0.33	INIT	
49	7 Classrooms 12-21 - Webster_02-07 Classroom - 18, West Wall	DWO-289-049	Drinking Fountain Bubbler	0.32	INIT	
50	7 Classrooms 12-21 - Webster_02-07 Classroom - 19, South Wall	DWO-289-050	Drinking Fountain Bubbler	0.32	INIT	
51	7 Classrooms 12-21 - Webster_02-07 Classroom - 20, South Wall	DWO-289-051	Drinking Fountain Bubbler	1.14	INIT	



Facility: Webster Elementary Report Type: Close Out Report Date of Report: 10/9/2018

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
52	7 Classrooms 12-21 - Webster_02-07 Classroom - 21, South Wall	DWO-289-052	Drinking Fountain Bubbler	0.32	INIT	
53	2 Admin/Supply - Webster_01-02 Faculty Workroom - WRK1, West Wall	DWO-289-053	Faucet	2.58	INIT	

#### \*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

#### \*\*Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.