

May 01, 2019

Emmitt Dodd
Principal
Fulton K-8 School
7055 Skyline Drive
San Diego, CA 92114

Subject: Fulton K-8 School Drinking Water Project Closeout

Dear Mr. Dodd:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Fulton K-8 campus.

As part of a district wide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Fulton School for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Fulton K-8 campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto
Manager, Facilities Planning



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin - Fulton_01-03 Common Area/Lounge - LGE1, West Wall	DWO-119-001	Faucet	33.34	FLTR	.238
2	3 Admin - Fulton_01-03 Nurse Office - HLC1, North Wall	DWO-119-002	Faucet	3.67	INIT	
3	2 Classrooms 1-6 - Fulton_01-02 Classroom - 01, East Wall	DWO-119-003	Drinking Fountain Bubblers	2.88	INIT	
4	2 Classrooms 1-6 - Fulton_01-02 Classroom - 02, East Wall	DWO-119-004	Drinking Fountain Bubblers	5.37	FLTR	ND
5	2 Classrooms 1-6 - Fulton_01-02 Classroom - 03, East Wall	DWO-119-005	Drinking Fountain Bubblers	5.21	FLTR	ND
6	2 Classrooms 1-6 - Fulton_01-02 Classroom - 04, West Wall	DWO-119-006	Drinking Fountain Bubblers	ND	INIT	
7	2 Classrooms 1-6 - Fulton_01-02 Classroom - 05, West Wall	DWO-119-007	Drinking Fountain Bubblers	3.37	INIT	
8	2 Classrooms 1-6 - Fulton_01-02 Classroom - 06, West Wall	DWO-119-008	Drinking Fountain Bubblers	5.11	FLTR	ND
9	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-009	Drinking Fountain Bubblers	4.32	INIT	
10	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-010	Drinking Fountain Bubblers	ND	INIT	
11	2 Classrooms 1-6 - Fulton_01-02 Building Exterior, South Wall	DWO-119-011	Drinking Fountain Bubblers	<5	INIT	
12	1 Classrooms 7-12 - Fulton_01-01 Classroom - 07, East Wall	DWO-119-012	Drinking Fountain Bubblers	ND	INIT	
13	1 Classrooms 7-12 - Fulton_01-01 Classroom - 08, East Wall	DWO-119-013	Drinking Fountain Bubblers	ND	INIT	
14	1 Classrooms 7-12 - Fulton_01-01 Classroom - 09, East Wall	DWO-119-014	Drinking Fountain Bubblers	2.71	INIT	
15	1 Classrooms 7-12 - Fulton_01-01 Classroom - 10, West Wall	DWO-119-015	Drinking Fountain Bubblers	2.94	INIT	
16	1 Classrooms 7-12 - Fulton_01-01 Classroom - 11, West Wall	DWO-119-016	Drinking Fountain Bubblers	2.89	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	1 Classrooms 7-12 - Fulton_01-01 Classroom - 12, West Wall	DWO-119-017	Drinking Fountain Bubblers	5.61	FLTR	ND
18	1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-018	Drinking Fountain Bubblers	6.07	PLMB	ND
19	1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-019	Drinking Fountain Bubblers	4.26	INIT	
20	1 Classrooms 7-12 - Fulton_01-01 Building Exterior, South Wall	DWO-119-020	Drinking Fountain Bubblers	3.71	INIT	
21	7 Classrooms 13-16 - Fulton_02-07 Classroom - 13, West Wall	DWO-119-021	Drinking Fountain Bubblers	ND	INIT	
22	7 Classrooms 13-16 - Fulton_02-07 Classroom - 14, West Wall	DWO-119-022	Drinking Fountain Bubblers	ND	INIT	
23	7 Classrooms 13-16 - Fulton_02-07 Classroom - 15, West Wall	DWO-119-023	Drinking Fountain Bubblers	ND	INIT	
24	7 Classrooms 13-16 - Fulton_02-07 Classroom - 16, West Wall	DWO-119-024	Drinking Fountain Bubblers	ND	INIT	
25	Portable A05 - Fulton Classroom - A05, West Wall	DWO-119-025	Drinking Fountain Bubblers	3.50	INIT	
26	Portable A04 - Fulton Classroom - A04, West Wall	DWO-119-026	Drinking Fountain Bubblers	2.59	INIT	
27	Portable A07 - Fulton Classroom - A07, East Wall	DWO-119-027	Drinking Fountain Bubblers	ND	INIT	
28	Portable B12/B13 - Fulton Science Prep Area - B13A, South Wall	DWO-119-028	Faucet	ND	INIT	
29	Portable Restrooms - Fulton Building Exterior, North Wall	DWO-119-029	Drinking Fountain Bubblers	ND	INIT	
30	Portable Restrooms - Fulton Building Exterior, North Wall	DWO-119-030	Drinking Fountain Bubblers	ND	INIT	
31	Portable Restrooms - Fulton Building Exterior, West side of BLDG	DWO-119-031	Drinking Fountain Bubblers	2.82	INIT	
32	Portable Restrooms - Fulton Building Exterior, West side of BLDG	DWO-119-032	Drinking Fountain Bubblers	<5	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Building Exterior, West Wall	DWO-119-033	Drinking Fountain Bubblers	3.05	INIT	
34	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Building Exterior, West Wall	DWO-119-034	Drinking Fountain Bubblers	<5	INIT	
35	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Kitchen, North Wall	DWO-119-035	Faucet	<5	INIT	
36	4 Auditorium/Cafeteria/Kitchen/Supply - Fulton_01-04 Lounge by Supply Rm, West Wall	DWO-119-036	Faucet	ND	INIT	
37	6 Library - Fulton_02-06 Office - OFS1, North Wall	DWO-119-037	Faucet	6.19	FLTR	ND
38	Portable B08 - Fulton Classroom - B08, West Wall	DWO-119-038	Drinking Fountain Bubblers	ND	INIT	
39	Portable B09 - Fulton Classroom - B09, East Wall	DWO-119-039	Drinking Fountain Bubblers	3.35	INIT	
40	Portable B10 - Fulton Classroom - B10, West Wall	DWO-119-040	Drinking Fountain Bubblers	3.64	INIT	
41	Portable B11 - Fulton Classroom - B11, East Wall	DWO-119-041	Drinking Fountain Bubblers	3.69	INIT	
42	5 Kinder Rms K01-K02 - Fulton_01-05 Classroom - K02, West Wall	DWO-119-042	Drinking Fountain Bubblers	5.57	PLMB	ND
43	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-043	Drinking Fountain Bubblers	19.58	FLTR	ND
44	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-044	Drinking Fountain Bubblers	5.51	FLTR	ND
45	5 Kinder Rms K01-K02 - Fulton_01-05 Building Exterior, East Wall	DWO-119-045	Drinking Fountain Bubblers	5.81	FLTR	ND
46	5 Kinder Rms K01-K02 - Fulton_01-05 Classroom - K01, West Wall	DWO-119-046	Drinking Fountain Bubblers	4.64	INIT	
47	3 Admin - Fulton_01-03 Faculty Workroom - WRK1, south wall	DWO-119-047	Faucet	10.51	PLMB	ND
48	Portable K03 - Fulton Restroom/Student Male - K03T2, island sink	DWO-119-048	Drinking Fountain Bubblers	ND	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fulton ES

Report Type: Closeout Report

Date of Report: 05/01/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.