

May 01, 2019

Alexa Greenland  
Executive Director  
Kavod Charter School  
6991 Balboa Ave  
San Diego, CA 92111

Subject: Kavod Charter School Drinking Water Project Closeout

Dear Mrs. Greenland:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Kavod campus.

As part of a district wide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Kavod Charter School for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Kavod Charter campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto  
Manager, Facilities Planning



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Closeout Report

Date of Report: 05/01/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Dining Area - 46, North Wall	DWO-175-001	Faucet	4.95	INIT	
2 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Kitchen - FSK2, South Wall	DWO-175-002	Faucet	ND	INIT	
3 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL1, North Wall West End	DWO-175-003	Drinking Fountain Bubblers	<5	INIT	
4 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL1, North Wall West End	DWO-175-004	Drinking Fountain Bubblers	2.93	INIT	
5 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall Center	DWO-175-005	Drinking Fountain Bubblers	3.56	INIT	
6 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall Center	DWO-175-006	Drinking Fountain Bubblers	ND	INIT	
7 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Conference Room - CON5, East Wall	DWO-175-007	Faucet	7.46	FLTR	ND
8 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Faculty Workroom - WRK2, East Wall	DWO-175-008	Faucet	5.53	FLTR	ND
9 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Faculty Workroom - WRK1, West Wall	DWO-175-009	Faucet	4.86	INIT	
10 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Office Principal, East Wall	DWO-175-010	Faucet	56.07	FLTR	ND
11 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Conference Room - CON1, South Wall	DWO-175-011	Faucet	6.23	FLTR	ND
12 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-012	Drinking Fountain Bubblers	4.50	INIT	
13 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-013	Drinking Fountain Bubblers	4.42	INIT	
14 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-014	Drinking Fountain Bubblers	ND	INIT	
15 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom/Non-Standard - RCT1, South Wall	DWO-175-015	Drinking Fountain Bubblers	6.12	FLTR	ND
16 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 71, North Wall	DWO-175-016	Drinking Fountain Bubblers	<5	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Building Exterior, East Wall	DWO-175-017	Drinking Fountain Bubblers	5.53	FLTR	ND
18	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Building Exterior, East Wall	DWO-175-018	Drinking Fountain Bubblers	4.92	INIT	
19	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Training Kitchen- 74A, South Wall	DWO-175-019	Faucet	3.69	INIT	
20	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL4, East Wall Center	DWO-175-020	Drinking Fountain Bubblers	11.04	FLTR	ND
21	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL4, East Wall Center	DWO-175-021	Drinking Fountain Bubblers	9.46	FLTR	ND
22	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 75, South Wall	DWO-175-022	Drinking Fountain Bubblers	4.79	INIT	
23	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 51, South Wall	DWO-175-023	Drinking Fountain Bubblers	4.32	INIT	
24	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 53, North Wall	DWO-175-024	Drinking Fountain Bubblers	4.51	INIT	
25	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 52, North Wall	DWO-175-025	Drinking Fountain Bubblers	5.12	FLTR	ND
26	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 50, South Wall	DWO-175-026	Drinking Fountain Bubblers	4.77	INIT	
27	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL3, East Wall North End	DWO-175-027	Drinking Fountain Bubblers	4.23	INIT	
28	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL3, East Wall North End	DWO-175-028	Drinking Fountain Bubblers	<5	INIT	
29	Portable B55 - Kavod Classroom/Non-Standard - B55, North Wall	DWO-175-029	Faucet	4.77	INIT	
30	Portable B55 - Kavod Storage/General - STO1, South End Of Room In Service	DWO-175-030	Faucet	5.94	RMOV	NA
31	Portable B57 - Kavod Classroom - B57, Ne Corner	DWO-175-031	Drinking Fountain Bubblers	ND	INIT	
32	Portable B59 - Kavod Classroom - B59, Ne Corner	DWO-175-032	Drinking Fountain Bubblers	4.63	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33	Portable B61 - Kavod Classroom - B61, Ne Corner	DWO-175-033	Drinking Fountain Bubblers	3.56	INIT	
34	Portable B58 - Kavod Classroom - B58, Sw Corner	DWO-175-034	Drinking Fountain Bubblers	4.19	INIT	
35	Portable B56 - Kavod Classroom - B56, Sw Corner	DWO-175-035	Drinking Fountain Bubblers	14.30	RMOV	NA
36	Portable B54 - Kavod Classroom - B54, Sw Corner	DWO-175-036	Drinking Fountain Bubblers	5.21	FLTR	ND
37	Portable Restrooms - Kavod Building Exterior, South Wall	DWO-175-037	Drinking Fountain Bubblers	3.97	INIT	
38	Portable Restrooms - Kavod Building Exterior, South Wall	DWO-175-038	Drinking Fountain Bubblers	4.15	INIT	
39	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Office - 74, Northeast Corner Of Room	DWO-175-110	Faucet	3.65	INIT	

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.