



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Barnard Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173058	05/25/17	05:58 AM	SAMPLE 1	3710020-BJI-A	< 5	ug/L
W1173059	05/25/17	06:01 AM	SAMPLE 2	3710020-BJI-B	< 5	ug/L
W1173060	05/25/17	06:03 AM	SAMPLE 3	3710020-BJI-C	< 5	ug/L
W1173061	05/25/17	06:07 AM	SAMPLE 4	3710020-BJI-D	< 5	ug/L
W1173062	05/25/17	06:09 AM	SAMPLE 5	3710020-BJI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 600 bldg Classrooms 18-20, Wall mounted exterior (North of Bldg), between Boys & Girls RR, facing B28, dual bubbler fountain to the left of single fountain, left bubbler on
- SAMPLE 2 300 bldg Classrooms 9-14, Wall mounted exterior (South of Bldg), between Girls' RR & Room 317, facing blacktop, triple bubbler fountain, middle bubbler
- SAMPLE 3 400 bldg Classrooms 3-8, Wall mounted exterior (South of Bldg), between Girls' RR & Room 412, facing blacktop, dual bubbler fountain, right bubbler
- SAMPLE 4 Kindergarten, Rm K2, bubbler on left sink
- SAMPLE 5 Cafeteria/Auditorium, Wall mounted exterior (South of Bldg), facing lunch court, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist