



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/9/17

San Diego Unified School District  
**Birney Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168062	05/02/17	06:30 AM	SAMPLE 1	3710020-AJJ-A	19.0	ug/L
W1168063	05/02/17	06:30 AM	SAMPLE 2	3710020-AJJ-B	< 5	ug/L
W1168064	05/02/17	06:35 AM	SAMPLE 3	3710020-AJJ-C	< 5	ug/L
W1168065	05/02/17	06:35 AM	SAMPLE 4	3710020-AJJ-D	13.9	ug/L
W1168066	05/02/17	06:40 AM	SAMPLE 5	3710020-AJJ-E	9.48	ug/L

**Source**      **Source Description**

- SAMPLE 1 Cafeteria, Wall mounted exterior (North of Bldg), facing lunch court, two single bubbler fountains, upper right fountain
- SAMPLE 2 Kindergarten/Preschool, Rm K1, classroom sink facing Restrooms, center bubbler between two sink faucets
- SAMPLE 3 Wall mounted exterior behind the elevator (East of Bldg), next to Electrical Equipment Rm 911 & Girls RR, two single bubbler fountains, lower left fo
- SAMPLE 4 200 BLDG, Wall mounted exterior (North of Bldg), between Storage 202 & 201/Girls & Boys Restrooms, facing Blacktop/playground, triple bubbler f
- SAMPLE 5 300 BLDG, Wall mounted exterior (North of Bldg), between Girls & Boys Restrooms, facing blacktop, two single bubbler fountains, upper right fount

DLR= State Mandated Detection Limit for Reporting (DLR)= 5  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist