



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

San Diego Unified School District  
**CPMA Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173011	05/20/17	08:01 AM	SAMPLE 1	3710020-BJG-A	< 5	ug/L
W1173012	05/20/17	07:58 AM	SAMPLE 2	3710020-BJG-B	< 5	ug/L
W1173013	05/20/17	07:55 AM	SAMPLE 3	3710020-BJG-C	< 5	ug/L
W1173014	05/20/17	07:51 AM	SAMPLE 4	3710020-BJG-D	< 5	ug/L
W1173015	05/20/17	07:48 AM	SAMPLE 5	3710020-BJG-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    100/200 BLDG, East end of Bldgs, breezeway, East Facing, two single bubbler fountains, lower right fountain
- SAMPLE 2    300/400 bldg, East end of Bldgs, breezeway, East Facing, two single bubbler fountains, upper left fountain
- SAMPLE 3    400 Bldg at Custodial #2 between Boys and Girls RR, two dual bubbler fountains, left bubbler on right fountain
- SAMPLE 4    Boys PE, North/ East Exterior Wall, two single bubbler fountains, lower right fountain
- SAMPLE 5    Cafeteria/ Kitchen- Food Prep, faucet above three compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist