



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Crawford High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166088	04/12/17	06:20 AM	SAMPLE 1	3710020-ADI-A	< 5	ug/L
W1166089	04/12/17	06:15 AM	SAMPLE 2	3710020-ADI-B	< 5	ug/L
W1166090	04/12/17	06:10 AM	SAMPLE 3	3710020-ADI-C	< 5	ug/L
W1166091	04/12/17	06:05 AM	SAMPLE 4	3710020-ADI-D	< 5	ug/L
W1166092	04/12/17	06:00 AM	SAMPLE 5	3710020-ADI-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kitchen, south wall, southwest corner, 2 compartment sink, faucet
SAMPLE 2	BLDG 900, west wall near girls locker room, right bubbler on dual fixture
SAMPLE 3	BLDG 900, west wall near boys locker room, left bubbler on dual fixture
SAMPLE 4	BLDG 400, northwest side between restrooms, next to custodian locker, upper right bubbler
SAMPLE 5	BLDG 800 lower level, between restrooms and custodial locker 5, upper right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist