



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Curie Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170048	05/11/17	06:13 AM	SAMPLE 1	3710020-BFA-A	< 5	ug/L
W1170049	05/11/17	06:14 AM	SAMPLE 2	3710020-BFA-B	< 5	ug/L
W1170050	05/11/17	06:09 AM	SAMPLE 3	3710020-BFA-C	< 5	ug/L
W1170051	05/11/17	06:06 AM	SAMPLE 4	3710020-BFA-D	< 5	ug/L
W1170052	05/11/17	06:17 AM	SAMPLE 5	3710020-BFA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Classroom Bldg Rooms 7-10, North Side of building in front of girls RR, triple bubbler fountain, center bubbler
- SAMPLE 2 Classroom Bldg Rooms 7-10, West side of building next to boys RR, triple bubbler fountain, right bubbler
- SAMPLE 3 Classroom Bldg Rooms 1-6, In front of boy's RR, two single-bubbler fountains, upper left fountain
- SAMPLE 4 Classroom Bldg Rooms 1-6, In front of girl's restroom on east side of building, triple bubbler fountain, middle bubbler
- SAMPLE 5 Kindergarten Building, Outside in the play area between K1 and K2, two single bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist