



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17


San Diego Unified School District  
**Dana (5-6)**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173001	05/20/17	06:25 AM	SAMPLE 1	3710020-BJD-A	< 5	ug/L
W1173002	05/20/17	06:22 AM	SAMPLE 2	3710020-BJD-B	< 5	ug/L
W1173003	05/20/17	06:30 AM	SAMPLE 3	3710020-BJD-C	< 5	ug/L
W1173004	05/20/17	06:33 AM	SAMPLE 4	3710020-BJD-D	< 5	ug/L
W1173005	05/20/17	06:38 AM	SAMPLE 5	3710020-BJD-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    120s - Hallway C, 1st Floor, Wall mounted interior, in the hall way, between Boys RR & Classroom 121, facing Office 122, single bubbler fountain
- SAMPLE 2    200 - Hallway B-2, 2nd Floor, Wall mounted interior, in the hallway, between Boys RR & Janitor 212 Rm, facing Classroom 207, single bubbler fountain
- SAMPLE 3    150s - Hallway G, 1st Floor, Wall mounted interior, in the hallway, next to Girls RR, facing kitchen, single bubbler fountain
- SAMPLE 4    150s - Hallway G, 1st Floor, Wall mounted interior, in the hallway, next to Classroom 153, facing Cafeteria, single bubbler fountain
- SAMPLE 5    Multi Purpose Room, Wall mounted exterior (West of Bldg), facing Library, next to back staff parking lot, two single bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist