



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**de Portola Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169424	05/06/17	06:28 AM	SAMPLE 1	3710020-BEF-A	< 5	ug/L
W1169425	05/06/17	06:26 AM	SAMPLE 2	3710020-BEF-B	< 5	ug/L
W1169426	05/06/17	06:24 AM	SAMPLE 3	3710020-BEF-C	< 5	ug/L
W1169427	05/06/17	06:22 AM	SAMPLE 4	3710020-BEF-D	< 5	ug/L
W1169428	05/06/17	06:19 AM	SAMPLE 5	3710020-BEF-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Basketball court area east side of campus, Outside of courts next to bleachers, triple bubbler fountain, right bubbler
- SAMPLE 2      Bungalow RRs, North side of campus across asphalt area, two single bubbler fountains, upper left fountain
- SAMPLE 3      Lunch Arbor, Next to fenced washing area east facing wall, triple bubbler fountain middle bubbler
- SAMPLE 4      Restroom building, Back side of RR building across from Room #801, dual bubbler fountain, right bubbler
- SAMPLE 5      Media Center Building, In front of main entrance to Media Center, dual bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist