



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Edison Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168282	05/10/17	06:14 AM	SAMPLE 1	3710020-AHC-A	< 5	ug/L
W1168283	05/10/17	06:08 AM	SAMPLE 2	3710020-AHC-B	< 5	ug/L
W1168284	05/10/17	06:03 AM	SAMPLE 3	3710020-AHC-C	< 5	ug/L
W1168285	05/10/17	05:56 AM	SAMPLE 4	3710020-AHC-D	< 5	ug/L
W1168286	05/10/17	05:59 AM	SAMPLE 5	3710020-AHC-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    1000 Building (Main Office); Nurse's Office; single regular faucet
- SAMPLE 2    South end of Building 1000; Exterior S-facing wall; Lower L bubbler of 2 single fountains
- SAMPLE 3    West end of Restroom bldg. in front of restrooms and patio area; Lower L bubbler of 2 single fountains
- SAMPLE 4    5000 Bldg.,N end of campus two-storybuilding; Indoor single bubbler in Rm 5104
- SAMPLE 5    5000 Building; Outdoor N end of campus in pre-school and kindergarten area;Lower L bubbler of 2 single fountains

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist