



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/26/17

San Diego Unified School District
Ericson Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170033	05/16/17	06:03 AM	SAMPLE 1	3710020-BEH-A	< 5	ug/L
W1170034	05/16/17	06:10 AM	SAMPLE 2	3710020-BEH-B	< 5	ug/L
W1170035	05/16/17	06:13 AM	SAMPLE 3	3710020-BEH-C	< 5	ug/L
W1170036	05/16/17	06:05 AM	SAMPLE 4	3710020-BEH-D	< 5	ug/L
W1170037	05/16/17	06:07 AM	SAMPLE 5	3710020-BEH-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 40s bldg, Wall mounted exterior (South of Bldg), next to Girls' RR, facing blacktop, triple bubbler fountain, left bubbler
- SAMPLE 2 10s bldg, Wall mounted exterior (North of Bldg), next to Girls RR, facing playground, triple bubbler fountain, middle bubbler
- SAMPLE 3 50s bldg, Wall mounted exterior (North of Bldg), next to Room 53 & wall, facing blacktop, three single bubbler fountains, middle fountain
- SAMPLE 4 Cafeteria, Wall mounted exterior (West of Bldg), facing lunch court, triple bubbler fountain, left bubbler
- SAMPLE 5 MultiPurpose Room, Wall mounted interior (North of the Room), two single bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist