

Water Quality Chemistry Services Lead School Testing Report Date: 4/27/17

San Diego Unified School District Franklin Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166313	04/13/17	05:54 AM	SAMPLE 1	3710020-AEC-A	< 5	ug/L
W1166314	04/13/17	05:58 AM	SAMPLE 2	3710020-AEC-B	< 5	ug/L
W1166315	04/13/17	06:09 AM	SAMPLE 3	3710020-AEC-C	5.15	ug/L
W1166316	04/13/17	06:04 AM	SAMPLE 4	3710020-AEC-D	< 5	ug/L
W1166317	04/13/17	06:07 AM	SAMPLE 5	3710020-AEC-E	< 5	ug/L

Source	Source Description
SAMPLE 1	Rooms 1-6, hallway wall mount, next to ramp facing girls restroom, dual fountain, left bubbler (113-1)
SAMPLE 2	Rooms 7-12, hallway wall mount, between rooms 7 and 9, dual fountain, left bubbler (113-2)
SAMPLE 3	Portable rooms B7-B9, in room B9, bubbler at sink (113-3)
SAMPLE 4	Rooms 14-17,wall mount, between girls/boys restrooms, facing courtyard, lower left bubbler (113-4)
SAMPLE 5	Kindergarten, room 18, sink between storage and girls restroom, bubbler at sink (113-5)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L $\,$

Doug Campbell Senior Chemist