



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/12/17

San Diego Unified School District  
**Freese Elementary**

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164613	04/06/17	06:29 AM	SAMPLE 1	3710020-ACA-A	< 5	ug/L
W1164614	04/06/17	06:25 AM	SAMPLE 2	3710020-ACA-B	< 5	ug/L
W1164615	04/06/17	06:16 AM	SAMPLE 3	3710020-ACA-C	< 5	ug/L
W1164616	04/06/17	06:12 AM	SAMPLE 4	3710020-ACA-D	< 5	ug/L
W1164617	04/06/17	06:21 AM	SAMPLE 5	3710020-ACA-E	< 5	ug/L

- SAMPLE 1 two story BLDG w/rooms 27-34, exterior, 1st floor, between girls/boys restrooms, facing blacktop, lower left bubbler
- SAMPLE 2 Cafeteria exterior, between storage 4 & supply rooms, facing library courtyard
- SAMPLE 3 rooms 10-13, ext next to room 13, facing library courtyard, lower left bubbler
- SAMPLE 4 Main BLDG, room 2, classroom sinks, next to exit, bubbler on left sink
- SAMPLE 5 Rooms 4-9, exterior between boys/girls restrooms, triple fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DI  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist