



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Hancock Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168771	04/28/17	06:10 AM	SAMPLE 1	3710020-BCF-A	< 5	ug/L
W1168772	04/28/17	06:10 AM	SAMPLE 2	3710020-BCF-B	< 5	ug/L
W1168773	04/28/17	06:15 AM	SAMPLE 3	3710020-BCF-C	< 5	ug/L
W1168774	04/28/17	06:15 AM	SAMPLE 4	3710020-BCF-D	< 5	ug/L
W1168775	04/28/17	06:20 AM	SAMPLE 5	3710020-BCF-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kitchen, Southeast inside cafeteria, faucet above two compartment sink
- SAMPLE 2 Cafeteria, Southeast inside cafeteria, southeast corner, single bubbler fountain
- SAMPLE 3 Building 3, Outside of rooms 30 and 21 next to RRs, two single bubbler fountains, lower left fountain
- SAMPLE 4 Building 2, North end of Building, triple bubbler fountain, center bubbler
- SAMPLE 5 Building 1, Inside Room 1, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist