



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17


San Diego Unified School District
Hawthorne Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170053	05/20/17	07:18 AM	SAMPLE 1	3710020-BFB-A	< 5	ug/L
W1170054	05/20/17	07:13 AM	SAMPLE 2	3710020-BFB-B	< 5	ug/L
W1170055	05/20/17	07:10 AM	SAMPLE 3	3710020-BFB-C	< 5	ug/L
W1170056	05/20/17	07:23 AM	SAMPLE 4	3710020-BFB-D	< 5	ug/L
W1170057	05/20/17	07:27 AM	SAMPLE 5	3710020-BFB-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten Building, West side of campus outside between K-1 and K-2, Sink with bubbler on right side
- SAMPLE 2 Building 2, West side of campus near room 6 (east facing wall), triple bubbler fountain, middle bubbler
- SAMPLE 3 Building 4, East side of building 4 near room 12, dual bubbler fountain next to single bubbler fountain, right bubbler on dual fountain
- SAMPLE 4 Cafeteria Building, North facing wall in front of cafeteria, two triple bubbler fountains, right fountain, center bubbler
- SAMPLE 5 outside Restroom bungalow on far east side of campus, dual bubbler fountain next to single bubbler fountain, left bubbler on dual fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist