



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/4/17

San Diego Unified School District  
**Hickman Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168388	04/25/17	06:32 AM	SAMPLE 1	3710020-BAH-A	< 5	ug/L
W1168389	04/25/17	06:35 AM	SAMPLE 2	3710020-BAH-B	< 5	ug/L
W1168390	04/25/17	06:40 AM	SAMPLE 3	3710020-BAH-C	5.02	ug/L
W1168391	04/25/17	06:42 AM	SAMPLE 4	3710020-BAH-D	< 5	ug/L
W1168392	04/25/17	06:47 AM	SAMPLE 5	3710020-BAH-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Hickman Hall, Sink in the Prep Kitchen (South of Bldg), faucet above single basin sink
- SAMPLE 2      Hickman Hall, Wall mounted exterior (South of Bldg), outside of Prep Kitchen, facing lunch court, triple bubbler fountain, left bubbler
- SAMPLE 3      10s Bldg (Rms 10-16), Wall mounted exterior (South of Bldg), between Girls RR & Custodian closet, facing grass courtyard, triple bubbler fountain, right bubbler
- SAMPLE 4      20s Bldg (Rms 21-26), Wall mounted exterior (West of Bldg), between Girls RR & Custodian closet, facing Blacktop, triple bubbler fountain, middle bubbler
- SAMPLE 5      40s Bldg (Rms 41-46), Wall mounted exterior (North of Bldg), between Girls RR & Custodian closet, facing Playground, triple bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist