



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

San Diego Unified School District  
**Holmes Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170221	05/25/17	06:06 AM	SAMPLE 1	3710020-CAJ-A	< 5	ug/L
W1170222	05/25/17	06:14 AM	SAMPLE 2	3710020-CAJ-B	< 5	ug/L
W1170223	05/25/17	06:09 AM	SAMPLE 3	3710020-CAJ-C	< 5	ug/L
W1170224	05/25/17	06:12 AM	SAMPLE 4	3710020-CAJ-D	< 5	ug/L
W1170225	05/25/17	06:01 AM	SAMPLE 5	3710020-CAJ-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Outside Auditorium next to lunch court, two single bubbler fountains, upper right fountain
- SAMPLE 2      Inside Kitchen, faucet above 2 compartment sink
- SAMPLE 3      Room 9, Outside fountain next to room 9 and bathrooms, triple bubbler fountain, middle bubbler
- SAMPLE 4      room 3, Outside fountain next to room 3 and bathrooms, quadrupel bubbler fountain, far right bubbler
- SAMPLE 5      Room K-1, Outside playground in front of K-1, bubbler on long sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist