



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17
San Diego Unified School District
Horton Elementary School

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1163972	04/04/17	05:59 AM	SAMPLE 1	3710020-ABA-A	< 5	ug/L
W1163973	04/04/17	06:03 AM	SAMPLE 2	3710020-ABA-B	< 5	ug/L
W1163974	04/04/17	06:15 AM	SAMPLE 3	3710020-ABA-C	< 5	ug/L
W1163975	04/04/17	06:11 AM	SAMPLE 4	3710020-ABA-D	< 5	ug/L
W1163976	04/04/17	06:06 AM	SAMPLE 5	3710020-ABA-E	< 5	ug/L

- SAMPLE 1 Kindergarten play area, South Wall, wall mount, left bubbler (149-01)
SAMPLE 2 Cafeteria lunch court, South wall, triple fountain, right bubbler (149-02)
SAMPLE 3 Between restroom boys 104 and girls 103 west wall hall, triple fountain, right bubbler (149-03)
SAMPLE 4 Between restroom boys #2 and girls #2 , lower fountain (149-04)
SAMPLE 5 Cafeteria, Kithchen area, north wall, food prep faucet (149-05)

DLR= State Mandated Detection Limit for Reporting (E)
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist