



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Ibarra Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168348	05/04/17	06:01 AM	SAMPLE 1	3710020-BAF-A	< 5	ug/L
W1168349	05/04/17	06:05 AM	SAMPLE 2	3710020-BAF-B	< 5	ug/L
W1168350	05/04/17	06:15 AM	SAMPLE 3	3710020-BAF-C	< 5	ug/L
W1168351	05/04/17	06:12 AM	SAMPLE 4	3710020-BAF-D	< 5	ug/L
W1168352	05/04/17	06:10 AM	SAMPLE 5	3710020-BAF-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Library, Wall mounted exterior, facing Kinder Yard, two single bubbler fountains, lower left fountain
- SAMPLE 2 Rooms 104-101 Two-story bldg., Wall mounted exterior, 1st Floor, next to restrooms, hallway facing Multipurpose Bldg., two single bubbler fountains, lower left fountain
- SAMPLE 3 Elevator 2, Wall mounted exterior, behind Elevator bldg., facing stage/blacktop/lunch arbor, three single bubbler fountains, high middle fountain
- SAMPLE 4 Elevator 1, Wall mounted exterior, behind Elevator bldg., facing blacktop, three single bubbler fountains, lower left fountain
- SAMPLE 5 Rooms 112-109 Two-story bldg., Wall mounted exterior, next to RR, facing stairs, two single bubbler fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist