



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

San Diego Unified School District  
**Innovation Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173006	05/20/17	08:26 AM	SAMPLE 1	3710020-BJF-A	< 5	ug/L
W1173007	05/20/17	08:29 AM	SAMPLE 2	3710020-BJF-B	< 5	ug/L
W1173008	05/20/17	08:34 AM	SAMPLE 3	3710020-BJF-C	< 5	ug/L
W1173009	05/20/17	08:40 AM	SAMPLE 4	3710020-BJF-D	< 5	ug/L
W1173010	05/20/17	08:19 AM	SAMPLE 5	3710020-BJF-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Classrooms 1-6 bldg, East end of Bldg between Staff and Student RRs, two single bubbler fountains, lower left fountain
- SAMPLE 2      Classrooms 7-12 bldg, East end of bldg between Student RRs, two single bubbler fountains, upper right fountain
- SAMPLE 3      Lunch Court, : East Exterior Wall, two single bubbler fountains, upper right fountain
- SAMPLE 4      Kitchen Prep Area, East Interior Wall, faucet above three compartment sink
- SAMPLE 5      Room 14, next to Nurse office and Custodial office, North Exterior Wall, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist