



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Jones Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169343	04/29/17	06:56 AM	SAMPLE 1	3710020-BDB-A	< 5	ug/L
W1169344	04/29/17	06:48 AM	SAMPLE 2	3710020-BDB-B	< 5	ug/L
W1169345	04/29/17	06:52 AM	SAMPLE 3	3710020-BDB-C	< 5	ug/L
W1169346	04/29/17	07:03 AM	SAMPLE 4	3710020-BDB-D	< 5	ug/L
W1169347	04/29/17	07:00 AM	SAMPLE 5	3710020-BDB-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten bldg, West exterior side between K-1 & K-2, two single-bubbler fountains, lower left fountain
- SAMPLE 2 Auditorium/Multipurpose, East exterior wall between heater room & cafeteria door, two single-bubbler fountains, lower left fountain
- SAMPLE 3 Kitchen, West interior wall in kitchen, spray nozzle above single compartment sink
- SAMPLE 4 North-East exterior next to room 7 & P.E. Equipment room, triple bubbler fountain, left bubbler
- SAMPLE 5 South-East exterior wall close to room 12, two single-bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist