



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17


San Diego Unified School District
Juarez Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169338	04/29/17	07:17 AM	SAMPLE 1	3710020-BDA-A	< 5	ug/L
W1169339	04/29/17	07:24 AM	SAMPLE 2	3710020-BDA-B	5.02	ug/L
W1169340	04/29/17	07:26 AM	SAMPLE 3	3710020-BDA-C	< 5	ug/L
W1169341	04/29/17	07:28 AM	SAMPLE 4	3710020-BDA-D	< 5	ug/L
W1169342	04/29/17	07:30 AM	SAMPLE 5	3710020-BDA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten Bldg, Between K-1 & K-2 and next to girl's RR, two single bubbler fountains, lower left fountain
- SAMPLE 2 Classrooms 1-6 bldg, North-East end of building next to boy/girl RRs, triple bubbler fountain, right bubbler
- SAMPLE 3 Classrooms 9-12 bldg, East end of building next to boy's RR and P.E. Equipment room, triple bubbler fountain, right bubbler
- SAMPLE 4 Lunch Court, East exterior wall of kitchen next to lunch court, two single bubbler fountains, upper right fountain
- SAMPLE 5 Kitchen, East interior wall of kitchen, sink faucet head above 2 compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist