



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/28/17

San Diego Unified School District
Keiler Leadership

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167409	04/20/17	06:00 AM	SAMPLE 1	3710020-AGE-A	< 5	ug/L
W1167410	04/20/17	06:05 AM	SAMPLE 2	3710020-AGE-B	< 5	ug/L
W1167411	04/20/17	06:15 AM	SAMPLE 3	3710020-AGE-C	< 5	ug/L
W1167412	04/20/17	06:10 AM	SAMPLE 4	3710020-AGE-D	< 5	ug/L
W1167413	04/20/17	06:10 AM	SAMPLE 5	3710020-AGE-E	5.12	ug/L

Source **Source Description**

- SAMPLE 1 Wall mounted exterior, between Auditorium & Cafeteria, facing lunch area, dual bubbler fountain to the right of sink, left bubbler
- SAMPLE 2 Wall mounted exterior, 1st Floor, next to Equipment Room (H101A), facing Rooms 32-34, two single bubbler fountains, lower right fountain
- SAMPLE 3 Near Rooms 5-8, Wall mounted exterior, next to Boys Restroom, facing courtyard & 2-story bldg, dual bubbler fountain, right bubbler
- SAMPLE 4 Near Rooms 9-11, Wall mounted exterior, next to a room (storage), facing Library, dual bubbler fountain, left bubbler
- SAMPLE 5 P.E. Complex, Wall mounted exterior, between Boys Restroom and Coaches Office, dual bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist