



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Clay Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Workroom, East Wall	DWO-065-001	Faucet	10.64		
2	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Nurse First Aid, North Wall	DWO-065-002	Faucet	<5		
3	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - 04, East Wall	DWO-065-003	Drinking Fountain Bubblers	5.21		
4	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - 03, East Wall	DWO-065-004	Drinking Fountain Bubblers	5.33		
5	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - 02, East Wall	DWO-065-005	Drinking Fountain Bubblers	4.92		
6	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Building Exterior, West Wall	DWO-065-006	Drinking Fountain Bubblers	4.59		
7	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Building Exterior, West Wall	DWO-065-007	Drinking Fountain Bubblers	ND		
8	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Building Exterior, West Wall	DWO-065-008	Drinking Fountain Bubblers	<5		
9	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - 01, West Wall	DWO-065-009	Faucet	4.33		
10	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - 01, West Wall	DWO-065-010	Drinking Fountain Bubblers	3.35		
11	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Classroom - K01, South Wall	DWO-065-011	Drinking Fountain Bubblers	ND		
12	2 Admin/Classrooms 1-4/K01/Supply - Clay_01-02 Building Exterior, East Wall	DWO-065-012	Drinking Fountain Bubblers	<5		
13	Portable A01 - Clay Classroom - A01, North Wall	DWO-065-013	Drinking Fountain Bubblers	ND		
14	Portable A02 - Clay Classroom - A02, North Wall	DWO-065-014	Drinking Fountain Bubblers	ND		
15	Portable B01 - Clay Classroom - B01, East Wall	DWO-065-015	Faucet	ND		
16	Portable B02 - Clay Classroom - B02, East Wall	DWO-065-016	Faucet	ND		
17	Portable B03 - Clay Classroom - B03, East Wall	DWO-065-017	Faucet	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Clay Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18 Portable B04 - Clay Classroom - B04, East Wall	DWO-065-018	Drinking Fountain Bubblers	3.43		
19 Portable B05 - Clay Classroom - B05, South Wall	DWO-065-019	Drinking Fountain Bubblers	4.90		
20 Portable B06 - Clay Classroom - B06, West Wall	DWO-065-020	Drinking Fountain Bubblers	3.46		
21 Portable B07 - Clay Classroom - B07, West Wall	DWO-065-021	Drinking Fountain Bubblers	4.14		
22 Portable B08 - Clay Classroom - B08, West Wall	DWO-065-022	Drinking Fountain Bubblers	ND		
23 Portable B09 - Clay Classroom - B09, West Wall	DWO-065-023	Faucet	ND		
24 Portable B09 - Clay Classroom - B09, West Wall	DWO-065-024	Drinking Fountain Bubblers	3.21		
25 1 Classrooms 5-10/Library - Clay Classroom - 08, East Wall	DWO-065-025	Drinking Fountain Bubblers	2.60		
26 1 Classrooms 5-10/Library - Clay Classroom - 09, East Wall	DWO-065-026	Drinking Fountain Bubblers	3.07		
27 1 Classrooms 5-10/Library - Clay Classroom - 10, East Wall	DWO-065-027	Drinking Fountain Bubblers	2.62		
28 1 Classrooms 5-10/Library - Clay Building Exterior, West Wall Left Side	DWO-065-028	Drinking Fountain Bubblers	4.45		
29 1 Classrooms 5-10/Library - Clay Building Exterior, West Wall Middle	DWO-065-029	Drinking Fountain Bubblers	2.64		
30 1 Classrooms 5-10/Library - Clay Building Exterior, West Wall Right Side	DWO-065-030	Drinking Fountain Bubblers	<5		
31 1 Classrooms 5-10/Library - Clay Classroom - 05, West Wall	DWO-065-031	Drinking Fountain Bubblers	3.01		
32 1 Classrooms 5-10/Library - Clay Classroom - 06, West Wall	DWO-065-032	Drinking Fountain Bubblers	2.82		
33 1 Classrooms 5-10/Library - Clay Classroom - 07, West Wall	DWO-065-033	Drinking Fountain Bubblers	2.83		
34 3 Auditorium/Cafeteria/Kitchen - Clay_01-03 Kitchen, North Wall	DWO-065-034	Faucet	8.34		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Clay Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 3 Auditorium/Cafeteria/Kitchen - Clay_01-03 Building Exterior, South Wall	DWO-065-035	Drinking Fountain Bubbler	14.51		
36 3 Auditorium/Cafeteria/Kitchen - Clay_01-03 Building Exterior, South Wall	DWO-065-036	Drinking Fountain Bubbler	10.50		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.