



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Nurse Health Suite, W Wall Faucet	DWO-095-001	Faucet	3.87		
2	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Workroom in Office, E Wall Faucet	DWO-095-002	Faucet	2.60		
3	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Lounge, N Wall Bubbler/Cooler	DWO-095-003	Drinking Fountain Bubbler	NA		
4	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Lounge, N Wall Faucet	DWO-095-004	Faucet	2.97		
5	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, N Ext Wall Left Bubbler By Office A6	DWO-095-005	Drinking Fountain Bubbler	2.90		
6	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, N Ext Wall Right Bubbler By Office A6	DWO-095-006	Drinking Fountain Bubbler	3.06		
7	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Classroom - A01, W Wall	DWO-095-007	Drinking Fountain Bubbler	ND		
8	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Peer Review, Nw Wall	DWO-095-008	Faucet	ND		
9	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Classroom - A03, S Wall	DWO-095-009	Drinking Fountain Bubbler	ND		
10	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, S Wall, Left Bubbler By Boys Rr	DWO-095-010	Drinking Fountain Bubbler	ND		
11	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, S Wall, Middle Bubbler By Boys Rr	DWO-095-011	Drinking Fountain Bubbler	3.09		
12	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, S Wall, Right Bubbler By Boys Rr	DWO-095-012	Drinking Fountain Bubbler	<5		
13	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Workroom in Library, W Wall, Library Work Room	DWO-095-013	Faucet	13.59		
14	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Parent Rm, N Wall	DWO-095-014	Faucet	ND		
15	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, W Ext Wall, Left Bubbler @ Lunch Ct	DWO-095-015	Drinking Fountain Bubbler	ND		
16	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, W Ext Wall, Right Bubbler @ Lunch Ct	DWO-095-016	Drinking Fountain Bubbler	ND		
17	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, W Ext Wall, Left Bubbler By Admin Hall	DWO-095-017	Drinking Fountain Bubbler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Building Exterior, W Ext Wall, Right Bubbler By Admin Hall	DWO-095-018	Drinking Fountain Bubbler	<5		
19	A Admin/Aud/Cafe/Kitchen/Library/Supply - Euclid Kitchen, N Wall Prep Sink	DWO-095-019	Faucet	ND		
20	B Classrooms - Euclid_15-17 Classroom - B02, W Wall	DWO-095-020	Drinking Fountain Bubbler	3.75		
21	B Classrooms - Euclid_15-17 Classroom - B01, W Wall	DWO-095-021	Drinking Fountain Bubbler	3.76		
22	B Classrooms - Euclid_15-17 Fac Wrkrm - WRK1, S Wall, Prep Rm Between B1- B6	DWO-095-022	Faucet	10.61		
23	B Classrooms - Euclid_15-17 Classroom - B06, E Wall	DWO-095-023	Drinking Fountain Bubbler	3.45		
24	B Classrooms - Euclid_15-17 Classroom - B05, E Wall	DWO-095-024	Drinking Fountain Bubbler	4.66		
25	B Classrooms - Euclid_15-17 Library - LRN2, Alcove Sink	DWO-095-025	Drinking Fountain Bubbler	2.53		
26	B Classrooms - Euclid_15-17 Library - LRN2, N Wall Kitchen Sink	DWO-095-026	Faucet	ND		
27	C Classrooms - Euclid Classroom - C01, N Wall	DWO-095-027	Drinking Fountain Bubbler	ND		
28	C Classrooms - Euclid Classroom - C02, N Wall	DWO-095-028	Drinking Fountain Bubbler	ND		
29	C Classrooms - Euclid Storage/General - C03, S Wall	DWO-095-029	Faucet	4.45		
30	C Classrooms - Euclid Conference Room - C05, E Wall	DWO-095-030	Drinking Fountain Bubbler	3.24		
31	C Classrooms - Euclid Classroom - C06, Ne Wall	DWO-095-031	Drinking Fountain Bubbler	ND		
32	C Classrooms - Euclid Classroom - C07, S Wall	DWO-095-032	Drinking Fountain Bubbler	ND		
33	C Classrooms - Euclid Classroom - C08, S Wall	DWO-095-033	Drinking Fountain Bubbler	3.31		
34	C Classrooms - Euclid Classroom - C09, S Wall	DWO-095-034	Drinking Fountain Bubbler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 C Classrooms - Euclid Building Exterior, N Wall Ext Of Girls Rr, Left Bubbler	DWO-095-035	Drinking Fountain Bubbler	ND		
36 C Classrooms - Euclid Building Exterior, N Wall Ext Of Girls Rr, Right Bubbler	DWO-095-036	Drinking Fountain Bubbler	ND		
37 C Classrooms - Euclid Classroom - C10, N Wall	DWO-095-037	Drinking Fountain Bubbler	3.94		
38 C Classrooms - Euclid Classroom - C11, N Wall	DWO-095-038	Drinking Fountain Bubbler	6.03		
39 D Classrooms/Elevator - Euclid_17-23 Faculty Workroom, E Wall	DWO-095-039	Faucet	6.61		
40 D Classrooms/Elevator - Euclid_17-23 Classroom - D111, W Wall	DWO-095-040	Drinking Fountain Bubbler	ND		
41 D Classrooms/Elevator - Euclid_17-23 Classroom - D113, W Wall	DWO-095-041	Drinking Fountain Bubbler	ND		
42 D Classrooms/Elevator - Euclid_17-23 Classroom - D115, W Wall	DWO-095-042	Drinking Fountain Bubbler	ND		
43 D Classrooms/Elevator - Euclid_17-23 Classroom - D114, E Wall	DWO-095-043	Drinking Fountain Bubbler	ND		
44 D Classrooms/Elevator - Euclid_17-23 Classroom - D112, E Wall	DWO-095-044	Drinking Fountain Bubbler	ND		
45 D Classrooms/Elevator - Euclid_17-23 Classroom - D110, E Wall	DWO-095-045	Drinking Fountain Bubbler	ND		
46 D Classrooms/Elevator - Euclid_17-23 Hallway 1st Floor, West Side Of Hall, Left Bubbler By	DWO-095-046	Drinking Fountain Bubbler	ND		
47 D Classrooms/Elevator - Euclid_17-23 Hallway 1st Floor, West Side Of Hall, Right Bubbler By	DWO-095-047	Drinking Fountain Bubbler	<5		
48 D Classrooms/Elevator - Euclid_17-23 Classroom - D205, W Wall	DWO-095-048	Drinking Fountain Bubbler	ND		
49 D Classrooms/Elevator - Euclid_17-23 Classroom - D208, W Wall	DWO-095-049	Drinking Fountain Bubbler	2.79		
50 D Classrooms/Elevator - Euclid_17-23 Classroom - D210, W Wall	DWO-095-050	Drinking Fountain Bubbler	ND		
51 D Classrooms/Elevator - Euclid_17-23 Classroom - D212, W Wall	DWO-095-051	Drinking Fountain Bubbler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
52	D Classrooms/Elevator - Euclid_17-23 Classroom - D211, E Wall	DWO-095-052	Drinking Fountain Bubblers	2.88		
53	D Classrooms/Elevator - Euclid_17-23 Classroom - D209, E Wall	DWO-095-053	Drinking Fountain Bubblers	2.52		
54	D Classrooms/Elevator - Euclid_17-23 Classroom - D207, E Wall	DWO-095-054	Drinking Fountain Bubblers	ND		
55	D Classrooms/Elevator - Euclid_17-23 Hall 2nd Floor, West Side, Left Bubblers By Staff Rr'S	DWO-095-055	Drinking Fountain Bubblers	ND		
56	D Classrooms/Elevator - Euclid_17-23 Hall 2nd Floor, West Side, Right Bubblers By Staff Rr'S	DWO-095-056	Drinking Fountain Bubblers	ND		
57	Portable E14 - Euclid Classroom - E14, N Wall	DWO-095-057	Drinking Fountain Bubblers	4.94		
58	Portable E13 - Euclid Classroom - E13, N Wall	DWO-095-058	Drinking Fountain Bubblers	ND		
59	Portable E12 - Euclid Classroom - E12, W Wall	DWO-095-059	Drinking Fountain Bubblers	5.41		
60	Portable E11 - Euclid Classroom - E11, W Wall	DWO-095-060	Drinking Fountain Bubblers			
61	Portable E10 - Euclid Classroom - E10, W Wall (Pre School)	DWO-095-061	Drinking Fountain Bubblers	3.49		
62	Portable E09 - Euclid Classroom - E09, W Wall (Pre School)	DWO-095-062	Drinking Fountain Bubblers	ND		
63	Portable Restrooms - Euclid Building Exterior, North Exterior, Left Bubblers	DWO-095-063	Drinking Fountain Bubblers	4.85		
64	Portable Restrooms - Euclid Building Exterior, North Exterior, Right Bubblers	DWO-095-064	Drinking Fountain Bubblers	6.18		
65	Portable E08 - Euclid Classroom - E08, S Wall (Pre School)	DWO-095-065	Drinking Fountain Bubblers	ND		
66	Portable E07 - Euclid Classroom - E07, S Wall	DWO-095-066	Drinking Fountain Bubblers	4.19		
67	K Kinder Rms K01-K02 - Euclid_12-12 Classroom - K01, Ne Wall, Left Bubblers @ Lavatory	DWO-095-067	Drinking Fountain Bubblers	4.69		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
68	K Kinder Rms K01-K02 - Euclid_12-12 Classroom - K01, Ne Wall, Right Bubbler @ Lavatory	DWO-095-068	Drinking Fountain Bubbler	4.16		
69	K Kinder Rms K01-K02 - Euclid_12-12 Building Exterior, S Wall Exterior By K2	DWO-095-069	Drinking Fountain Bubbler	5.69		
70	K Kinder Rms K01-K02 - Euclid_12-12 Classroom - K02, Nw Wall, Left Bubbler @ Lavatory	DWO-095-070	Drinking Fountain Bubbler	4.27		
71	K Kinder Rms K01-K02 - Euclid_12-12 Classroom - K02, Nw Wall, Right Bubbler @ Lavatory	DWO-095-071	Drinking Fountain Bubbler	3.27		
72	K Kinder Rm K03 - Euclid_12-13 Building Exterior, West Exterior Wall Of K3, Left Bubbler	DWO-095-072	Drinking Fountain Bubbler	7.24		
73	K Kinder Rm K03 - Euclid_12-13 Building Exterior, West Exterior Wall Of K3, Right Bubbler	DWO-095-073	Drinking Fountain Bubbler	4.52		
74	K Kinder Rm K03 - Euclid_12-13 Classroom - K03, Ne Wall @ Right Lavatory	DWO-095-074	Drinking Fountain Bubbler	2.64		
75	Portable K04 - Euclid Classroom - K04, E Wall	DWO-095-075	Drinking Fountain Bubbler	3.77		
76	Portable K05 - Euclid Classroom - K05, Island Sink	DWO-095-076	Drinking Fountain Bubbler	2.59		
77	1 CCD Classrooms/Office - Euclid CDC_01-01 Common Area/Hallway - HAL2, West Wall	DWO-095-077	Drinking Fountain Bubbler	ND		
78	1 CCD Classrooms/Office - Euclid CDC_01-01 Lounge & Workroom, West Wall	DWO-095-078	Faucet	4.88		
79	1 CCD Classrooms/Office - Euclid CDC_01-01 Building Exterior, South Wall East Side Left	DWO-095-079	Drinking Fountain Bubbler	<5		
80	1 CCD Classrooms/Office - Euclid CDC_01-01 Building Exterior, South Wall East Side Right	DWO-095-080	Drinking Fountain Bubbler	5.07		
81	1 CCD Classrooms/Office - Euclid CDC_01-01 Building Exterior, South Wall West Side	DWO-095-081	Drinking Fountain Bubbler	3.89		
82	1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD2 School Age, East Wall Left	DWO-095-082	Drinking Fountain Bubbler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Euclid Elementary

Report Type: Progress Report

Date of Report: 11/16/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
83 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD2 School Age, East Wall Center Left	DWO-095-083	Drinking Fountain Bubblers	ND		
84 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD2 School Age, East Wall Center Right	DWO-095-084	Drinking Fountain Bubblers	ND		
85 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD2 School Age, East Wall Right	DWO-095-085	Drinking Fountain Bubblers	ND		
86 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD4 Art, East Wall	DWO-095-086	Drinking Fountain Bubblers	ND		
87 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD1 Preschool, West Wall Left	DWO-095-087	Drinking Fountain Bubblers	3.06		
88 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD1 Preschool, West Wall Center Left	DWO-095-088	Drinking Fountain Bubblers	ND		
89 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD1 Preschool, West Wall Center Right	DWO-095-089	Drinking Fountain Bubblers	ND		
90 1 CCD Classrooms/Office - Euclid CDC_01-01 Classroom - CCD1 Preschool, West Wall Right	DWO-095-090	Drinking Fountain Bubblers	ND		
91 1 CCD Classrooms/Office - Euclid CDC_01-01 Kitchen, West Wall	DWO-095-091	Faucet	4.09		
92 1 CCD Classrooms/Office - Euclid CDC_01-01 Isolation Office, West Wall	DWO-095-092	Faucet	3.03		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.