



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fletcher Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	2 Admin/Supply - Fletcher_01-02 Workroom, E WALL	DWO-105-001	Faucet	0.71		
2	2 Admin/Supply - Fletcher_01-02 Nurse 1st Aid, S WALL	DWO-105-002	Faucet	1.49		
3	1 Kinder Rms K01-K02 - Fletcher_01-01 Classroom - K02, TRGH RGHT	DWO-105-003	Drinking Fountain Bubblers	<5		
4	1 Kinder Rms K01-K02 - Fletcher_01-01 Classroom - K01, TRGH RGHT	DWO-105-004	Drinking Fountain Bubblers	<5		
5	1 Kinder Rms K01-K02 - Fletcher_01-01 Building Exterior, LFT BBLR	DWO-105-005	Drinking Fountain Bubblers	<5		
6	1 Kinder Rms K01-K02 - Fletcher_01-01 Building Exterior, RGHT BBLR	DWO-105-006	Drinking Fountain Bubblers	<5		
7	3 Auditorium/Cafeteria/Kitchen - Fletcher_01-03 Building Exterior, LFT BBLR	DWO-105-007	Drinking Fountain Bubblers	<5		
8	3 Auditorium/Cafeteria/Kitchen - Fletcher_01-03 Building Exterior, RGHT BBLR	DWO-105-008	Drinking Fountain Bubblers	2.09		
9	3 Auditorium/Cafeteria/Kitchen - Fletcher_01-03 Auditorium, SOUTH WALL	DWO-105-009	Drinking Fountain Bubblers	ND		
10	3 Auditorium/Cafeteria/Kitchen - Fletcher_01-03 Kitchen, N WALL	DWO-105-010	Faucet	45.30		
11	6 Library - Fletcher_02-06 Workroom, NE WALL	DWO-105-011	Faucet	1.07		
12	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 10, SW WALL	DWO-105-012	Drinking Fountain Bubblers	0.94		
13	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 11, NW WALL UPPER SNK	DWO-105-013	Faucet	1.38		
14	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 11, NW WALL LOWER SNK	DWO-105-014	Drinking Fountain Bubblers	4.28		
15	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 12, SW WALL	DWO-105-015	Drinking Fountain Bubblers	0.81		
16	4 Classrooms 7-12 - Fletcher_01-04 Building Exterior, LFT BBLR	DWO-105-016	Drinking Fountain Bubblers	6.82		
17	4 Classrooms 7-12 - Fletcher_01-04 Building Exterior, CNTR BBLR	DWO-105-017	Drinking Fountain Bubblers	0.75		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fletcher Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	4 Classrooms 7-12 - Fletcher_01-04 Building Exterior, RGHT BBLR	DWO-105-018	Drinking Fountain Bubler	1.67		
19	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 09, SE WALL	DWO-105-019	Drinking Fountain Bubler	7.90		
20	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 08, NE WALL	DWO-105-020	Drinking Fountain Bubler	4.50		
21	4 Classrooms 7-12 - Fletcher_01-04 Classroom - 07, SE WALL	DWO-105-021	Drinking Fountain Bubler	0.94		
22	5 Classrooms 1-6 - Fletcher_01-05 Classroom - 05, NW WALL	DWO-105-022	Faucet	6.81		
23	5 Classrooms 1-6 - Fletcher_01-05 Classroom - 06, SW WALL	DWO-105-023	Faucet	2.04		
24	5 Classrooms 1-6 - Fletcher_01-05 Building Exterior, LFT BBLR	DWO-105-024	Drinking Fountain Bubler	<5		
25	5 Classrooms 1-6 - Fletcher_01-05 Building Exterior, RGHT BBLR	DWO-105-025	Drinking Fountain Bubler	1.68		
26	5 Classrooms 1-6 - Fletcher_01-05 Classroom - 03, SE WALL	DWO-105-026	Drinking Fountain Bubler	1.33		
27	5 Classrooms 1-6 - Fletcher_01-05 Classroom - 02, NE WALL	DWO-105-027	Drinking Fountain Bubler	0.65		
28	5 Classrooms 1-6 - Fletcher_01-05 Classroom - 01, SE WALL	DWO-105-028	Drinking Fountain Bubler	2.01		
29	Portable B14 - Fletcher Classroom - B14, N WALL (RGHT FCT)	DWO-105-029	Faucet	7.97		
30	Portable B15 - Fletcher Classroom - B15, N WALL	DWO-105-030	Drinking Fountain Bubler	9.52		
31	Portable B16 - Fletcher Classroom - B16, N WALL	DWO-105-031	Drinking Fountain Bubler	2.78		
32	Portable B17 - Fletcher Classroom - B17, N WALL	DWO-105-032	Drinking Fountain Bubler	3.80		
33	Portable B18 - Fletcher Classroom - B18, N WALL	DWO-105-033	Drinking Fountain Bubler	4.43		
34	Portable CC1 - Fletcher CDC Classroom - CC1, SOUTH WALL, LEFT BUBBLER	DWO-105-034	Drinking Fountain Bubler	6.94		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Fletcher Elementary

Report Type: Progress Report

Date of Report: 11/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 Portable CC1 - Fletcher CDC Classroom - CC1, SOUTH WALL, RIGHT BUBBLER	DWO-105-035	Drinking Fountain Bubblers	<5		
36 Portable CC2 - Fletcher CDC Classroom - CC2, SOUTH WALL, LEFT BUBBLER	DWO-105-036	Drinking Fountain Bubblers	<5		
37 Portable CC2 - Fletcher CDC Classroom - CC2, SOUTH WALL, RIGHT BUBBLER	DWO-105-037	Drinking Fountain Bubblers	3.14		
38 Portable CC2 - Fletcher CDC Classroom - CC2, NORTH WALL BY RESTROOM	DWO-105-038	Drinking Fountain Bubblers	<5		
39 Portable CC2 - Fletcher CDC Classroom - CC2, WEST WALL	DWO-105-039	Faucet	1.64		
40 Portable CC1 - Fletcher CDC Classroom - CC1, EAST WALL	DWO-105-040	Faucet	7.24		
41 3 Auditorium/Cafeteria/Kitchen - Fletcher_01-03 Kitchen, N WALL	DWO-105-041	Faucet	3.66		
42 5 Classrooms 1-6 - Fletcher_01-05 Resource Teacher, W WALL	DWO-105-042	Faucet	9.19		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.