



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Garfield ES

Report Type: Progress Report

Date of Report: 12/14/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Nurse Office - HLC1, North wall	DWO-124-001	Drinking Fountain Bubblers	ND		
2	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Office - OFS1, SE wall	DWO-124-002	Drinking Fountain Bubblers	2.50		
3	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Auxiliary - CON3, south wall	DWO-124-003	Drinking Fountain Bubblers	ND		
4	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom/Non-Standard - RCT1, NE corner of room	DWO-124-004	Faucet	ND		
5	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 19, SW corner of room	DWO-124-005	Drinking Fountain Bubblers	ND		
6	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 18, SW corner of room	DWO-124-006	Drinking Fountain Bubblers	ND		
7	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 17, NW corner of room	DWO-124-007	Drinking Fountain Bubblers	ND		
8	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, NE wall	DWO-124-008	Drinking Fountain Bubblers	ND		
9	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, NE wall	DWO-124-009	Drinking Fountain Bubblers	ND		
10	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 16, SW corner of room	DWO-124-010	Drinking Fountain Bubblers	ND		
11	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 15, NW corner of room	DWO-124-011	Drinking Fountain Bubblers	2.51		
12	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 14, SW corner of room	DWO-124-012	Drinking Fountain Bubblers	ND		
13	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 13, NW corner of room	DWO-124-013	Drinking Fountain Bubblers	ND		
14	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 12, SW corner of room	DWO-124-014	Drinking Fountain Bubblers	ND		
15	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, SE wall	DWO-124-015	Drinking Fountain Bubblers	ND		
16	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, SE wall	DWO-124-016	Drinking Fountain Bubblers	ND		
17	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 11, NW corner of room	DWO-124-017	Drinking Fountain Bubblers	ND		



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Garfield ES

Report Type: Progress Report

Date of Report: 12/14/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Faculty Workroom - WRK3, south wall	DWO-124-018	Faucet	ND		
19	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Lounge, North wall	DWO-124-019	Drinking Fountain Bubblers	ND		
20	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Faculty Workroom - WRK2, North wall	DWO-124-020	Faucet	ND		
21	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 10, NE corner of room	DWO-124-021	Drinking Fountain Bubblers	ND		
22	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, South wall	DWO-124-022	Drinking Fountain Bubblers	<5		
23	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Building Exterior, South wall	DWO-124-023	Drinking Fountain Bubblers	ND		
24	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Food Services/Kitchen - FSK1, Center wall	DWO-124-024	Faucet	ND		
25	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 09, SW corner of room	DWO-124-025	Drinking Fountain Bubblers	ND		
26	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Common Area/Hallway - HAL1, SE side of hallway	DWO-124-026	Drinking Fountain Bubblers	ND		
27	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Common Area/Hallway - HAL1, SE side of hallway	DWO-124-027	Drinking Fountain Bubblers	<5		
28	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 08, NW corner of room	DWO-124-028	Drinking Fountain Bubblers	ND		
29	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 07, SW corner of room	DWO-124-029	Drinking Fountain Bubblers	ND		
30	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 06, NW corner of room	DWO-124-030	Drinking Fountain Bubblers	ND		
31	6 Admin/Class/Library/Kitchen/Supply - Garfield ES Classroom - 05, SW corner of room	DWO-124-031	Drinking Fountain Bubblers	ND		
32	Portable B20/B21 - Garfield ES Classroom - B20, SW corner of room	DWO-124-032	Drinking Fountain Bubblers	3.65		
33	Portable B20/B21 - Garfield ES Classroom - B21, SE corner of room	DWO-124-033	Drinking Fountain Bubblers	3.43		
34	Portable B22/B23 - Garfield ES Classroom - B22, SW corner of room	DWO-124-034	Drinking Fountain Bubblers	3.84		



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Garfield ES

Report Type: Progress Report

Date of Report: 12/14/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 Portable B22/B23 - Garfield ES Classroom - B23, SE corner of room	DWO-124-035	Drinking Fountain Bubblers	3.15		
36 8 Class 3-4 - Garfield ES_07-08 Classroom - 04, North wall of room	DWO-124-036	Drinking Fountain Bubblers	ND		
37 8 Class 3-4 - Garfield ES_07-08 Classroom - 03, South wall of room	DWO-124-037	Drinking Fountain Bubblers	ND		
38 Portable B01/B02 - Garfield ES Classroom - B02, SW corner of room	DWO-124-038	Drinking Fountain Bubblers	17.28		
39 Portable B01/B02 - Garfield ES Classroom - B01, SE corner of room	DWO-124-039	Drinking Fountain Bubblers	11.83		
40 Portable CC4 - Garfield ES Classroom - CC4, East side of room	DWO-124-040	Drinking Fountain Bubblers	ND		
41 Portable CC4 - Garfield ES Classroom - CC4, East side of room	DWO-124-041	Drinking Fountain Bubblers	3.31		
42 Portable CC3 - Garfield ES Classroom - CC3, East side of room	DWO-124-042	Drinking Fountain Bubblers	<5		
43 Portable CC2 - Garfield ES Classroom - CC2, North side of room	DWO-124-043	Drinking Fountain Bubblers	4.89		
44 Portable CC5 Office - Garfield ES Office in CC5, Center wall	DWO-124-044	Drinking Fountain Bubblers	<5		
45 5 Classroom CC1 - Garfield ES_05-05 Restroom/Student Female - CC1T1, South wall	DWO-124-045	Faucet	ND		
46 Portable B24 - Garfield ES Classroom - B24, NE corner of room	DWO-124-046	Drinking Fountain Bubblers	9.78		
47 Portable B25 - Garfield ES Classroom - B25, NW corner of room	DWO-124-047	Drinking Fountain Bubblers	10.57		
48 6 Admin/Class/Library/Kitchen/Supply - Garfield ES Nurse Office - HLC1, North wall	DWO-124-048	Faucet	2.69		
49 6 Admin/Class/Library/Kitchen/Supply - Garfield ES Office - OFS1, SE wall	DWO-124-049	Faucet	ND		
50 6 Admin/Class/Library/Kitchen/Supply - Garfield ES Auxiliary - CON3, south wall	DWO-124-050	Faucet	ND		
51 6 Admin/Class/Library/Kitchen/Supply - Garfield ES Lounge, North wall	DWO-124-051	Faucet	ND		



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Garfield ES

Report Type: Progress Report

Date of Report: 12/14/2018

52

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
Portable CC5 Office - Garfield ES Office in CC5, Center wall	DWO-124-052	Faucet	3.50		

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.