



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Progress Report

Date of Report: 02/07/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Dining Area - 46, North Wall	DWO-175-001	Faucet	4.95		
2 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Kitchen - FSK2, South Wall	DWO-175-002	Faucet	ND		
3 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL1, North Wall West End	DWO-175-003	Drinking Fountain Bubblers	<5		
4 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL1, North Wall West End	DWO-175-004	Drinking Fountain Bubblers	2.93		
5 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall Center	DWO-175-005	Drinking Fountain Bubblers	3.56		
6 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall Center	DWO-175-006	Drinking Fountain Bubblers	ND		
7 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Conference Room - CON5, East Wall	DWO-175-007	Faucet	7.46		
8 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Faculty Workroom - WRK2, East Wall	DWO-175-008	Faucet	5.53		
9 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Faculty Workroom - WRK1, West Wall	DWO-175-009	Faucet	4.86		
10 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Office Principal, East Wall	DWO-175-010	Faucet	56.07		
11 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Conference Room - CON1, South Wall	DWO-175-011	Faucet	6.23		
12 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-012	Drinking Fountain Bubblers	4.50		
13 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-013	Drinking Fountain Bubblers	4.42		
14 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL2, North Wall East End	DWO-175-014	Drinking Fountain Bubblers	ND		
15 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom/Non-Standard - RCT1, South Wall	DWO-175-015	Drinking Fountain Bubblers	6.12		
16 Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 71, North Wall	DWO-175-016	Drinking Fountain Bubblers	<5		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Progress Report

Date of Report: 02/07/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Building Exterior, East Wall	DWO-175-017	Drinking Fountain Bubblers	5.53		
18	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Building Exterior, East Wall	DWO-175-018	Drinking Fountain Bubblers	4.92		
19	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Food Services/Training Kitchen- 74A, South Wall	DWO-175-019	Faucet	3.69		
20	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL4, East Wall Center	DWO-175-020	Drinking Fountain Bubblers	11.04		
21	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL4, East Wall Center	DWO-175-021	Drinking Fountain Bubblers	9.46		
22	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 75, South Wall	DWO-175-022	Drinking Fountain Bubblers	4.79		
23	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 51, South Wall	DWO-175-023	Drinking Fountain Bubblers	4.32		
24	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 53, North Wall	DWO-175-024	Drinking Fountain Bubblers	4.51		
25	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 52, North Wall	DWO-175-025	Drinking Fountain Bubblers	5.12		
26	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Classroom - 50, South Wall	DWO-175-026	Drinking Fountain Bubblers	4.77		
27	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL3, East Wall North End	DWO-175-027	Drinking Fountain Bubblers	4.23		
28	Admin/Classrooms/Kitchen/Supply - Kavod_01-01 Common Area/Hallway - HAL3, East Wall North End	DWO-175-028	Drinking Fountain Bubblers	<5		
29	Portable B55 - Kavod Classroom/Non-Standard - B55, North Wall	DWO-175-029	Faucet	4.77		
30	Portable B55 - Kavod Storage/General - STO1, South End Of Room In Service	DWO-175-030	Faucet	5.94		
31	Portable B57 - Kavod Classroom - B57, Ne Corner	DWO-175-031	Drinking Fountain Bubblers	ND		
32	Portable B59 - Kavod Classroom - B59, Ne Corner	DWO-175-032	Drinking Fountain Bubblers	4.63		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Kavod @ Lindbergh/Schweitzer

Report Type: Progress Report

Date of Report: 02/07/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33 Portable B61 - Kavod Classroom - B61, Ne Corner	DWO-175-033	Drinking Fountain Bubblers	3.56		
34 Portable B58 - Kavod Classroom - B58, Sw Corner	DWO-175-034	Drinking Fountain Bubblers	4.19		
35 Portable B56 - Kavod Classroom - B56, Sw Corner	DWO-175-035	Drinking Fountain Bubblers	14.30		
36 Portable B54 - Kavod Classroom - B54, Sw Corner	DWO-175-036	Drinking Fountain Bubblers	5.21		
37 Portable Restrooms - Kavod Building Exterior, South Wall	DWO-175-037	Drinking Fountain Bubblers	3.97		
38 Portable Restrooms - Kavod Building Exterior, South Wall	DWO-175-038	Drinking Fountain Bubblers	4.15		

***Action levels and color indication**

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

****Clearance actions**

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.