



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Pacific Beach Elementary

Report Type: Progress Report

Date of Report: 11/27/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 Restrooms - Seaside_02-05 Building Exterior, North Wall	DWO-227-001	Drinking Fountain Bubblers	ND		
2 Restrooms - Seaside_02-05 Building Exterior, North Wall	DWO-227-002	Drinking Fountain Bubblers	6.54		
3 Office - Seaside_02-02 Lounge, West Wall	DWO-227-003	Faucet	ND		
4 Office - Seaside_02-02 Isolation, North Wall	DWO-227-004	Faucet	3.87		
5 Office - Seaside_02-02 Food Serving, North Wall	DWO-227-005	Faucet	16.00		
6 Classroom CCD1 - Seaside_02-03 Classroom - CCD1, East Wall	DWO-227-006	Drinking Fountain Bubblers	ND		
7 Classroom CCD2 - Seaside_02-04 Classroom - CCD2, West Wall	DWO-227-007	Drinking Fountain Bubblers	ND		
8 3 Admin/Classrooms 12-16/Library/Supply - PB Elem Nurse Health, W WALL	DWO-227-008	Faucet	16.40		
9 3 Admin/Classrooms 12-16/Library/Supply - PB Elem Workroom in Office, E WALL	DWO-227-009	Faucet	2.36		
10 3 Admin/Classrooms 12-16/Library/Supply - PB Elem Workroom in Library, N WALL	DWO-227-010	Faucet	48.40		
11 3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 16, W WALL	DWO-227-011	Drinking Fountain Bubblers	1.79		
12 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Building Exterior, NW EXTERIOR LEFT BUBBLER	DWO-227-012	Drinking Fountain Bubblers	2.13		
13 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Building Exterior, NW EXTERIOR RIGHT BUBBLER	DWO-227-013	Drinking Fountain Bubblers	1.68		
14 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Hallway, S HALL WALL BY CAFE LEFT	DWO-227-014	Drinking Fountain Bubblers	<5		
15 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Hallway, S HALL WALL BY CAFE RIGHT	DWO-227-015	Drinking Fountain Bubblers	1.86		
16 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Music Rm, S WALL	DWO-227-016	Faucet	2.64		
17 6 Auditorium/Cafeteria/Kitchen - PB Elem_06-06 Kitchen, S WALL	DWO-227-017	Spray Faucet	3.42		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Pacific Beach Elementary

Report Type: Progress Report

Date of Report: 11/27/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	Portable B18 - PB Elem Classroom - B18, W WALL	DWO-227-018	Drinking Fountain Bubblers	0.74		
19	Portable B17 - PB Elem Classroom - B17, W WALL	DWO-227-019	Drinking Fountain Bubblers	0.84		
20	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Vestibule @ Faculty RR's, N WALL LEFT BUBBLER	DWO-227-020	Drinking Fountain Bubblers	0.85		
21	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Vestibule @ Faculty RR's, N WALL RIGHT BUBBLER	DWO-227-021	Drinking Fountain Bubblers	0.82		
22	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 15, W WALL	DWO-227-022	Faucet	7.39		
23	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 13, N WALL	DWO-227-023	Drinking Fountain Bubblers	1.87		
24	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 12, N WALL	DWO-227-024	Faucet	1.16		
25	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 12, N WALL	DWO-227-025	Drinking Fountain Bubblers	<5		
26	3 Admin/Classrooms 12-16/Library/Supply - PB Elem Classroom - 14, S WALL	DWO-227-026	Drinking Fountain Bubblers	1.34		
27	5 Classrooms 5-11 - PB Elem_05-05 Classroom - 11, W WALL	DWO-227-027	Drinking Fountain Bubblers	2.49		
28	5 Classrooms 5-11 - PB Elem_05-05 Resource Rm, S WALL	DWO-227-028	Faucet	1.64		
29	5 Classrooms 5-11 - PB Elem_05-05 Classroom - 09, E WALL	DWO-227-029	Faucet	0.98		
30	5 Classrooms 5-11 - PB Elem_05-05 Corridor, E WALL LEFT BUBBLER	DWO-227-030	Drinking Fountain Bubblers	4.10		
31	5 Classrooms 5-11 - PB Elem_05-05 Corridor, E WALL RIGHT BUBBLER	DWO-227-031	Drinking Fountain Bubblers	0.85		
32	5 Classrooms 5-11 - PB Elem_05-05 Classroom - 08, W WALL	DWO-227-032	Drinking Fountain Bubblers	2.56		
33	5 Classrooms 5-11 - PB Elem_05-05 Classroom - 07, E WALL	DWO-227-033	Drinking Fountain Bubblers	1.41		
34	5 Classrooms 5-11 - PB Elem_05-05 Classroom - 06, W WALL	DWO-227-034	Drinking Fountain Bubblers	1.31		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Pacific Beach Elementary

Report Type: Progress Report

Date of Report: 11/27/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 5 Classrooms 5-11 - PB Elem_05-05 Classroom - 05, E WALL	DWO-227-035	Drinking Fountain Bubler	1.34		
36 5 Classrooms 5-11 - PB Elem_05-05 Building Exterior, W WALL, LEFT BUBBLER	DWO-227-036	Drinking Fountain Bubler	<5		
37 5 Classrooms 5-11 - PB Elem_05-05 Building Exterior, W WALL, MIDDLE BUBBLER	DWO-227-037	Drinking Fountain Bubler	1.31		
38 5 Classrooms 5-11 - PB Elem_05-05 Building Exterior, W WALL, RIGHT BUBBLER	DWO-227-038	Drinking Fountain Bubler	0.85		
39 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Classroom - 04, E WALL	DWO-227-039	Drinking Fountain Bubler	3.32		
40 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Classroom - 03, E WALL	DWO-227-040	Drinking Fountain Bubler	2.84		
41 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Classroom - K02, W WALL	DWO-227-041	Drinking Fountain Bubler	<5		
42 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Building Exterior, N WALL LEFT BUBBLER	DWO-227-042	Drinking Fountain Bubler	3.33		
43 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Building Exterior, N WALL RIGHT BUBBLER	DWO-227-043	Drinking Fountain Bubler	<5		
44 7 Classrooms 3-4/K01-K02 - PB Elem_07-07 Classroom - K01, E WALL	DWO-227-044	Drinking Fountain Bubler	0.93		
45 Portable K - PB Elem Classroom - K, W WALL	DWO-227-045	Drinking Fountain Bubler	1.13		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.