



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Perry ES

Report Type: Progress Report

Date of Report: 2/28/2019

| Location   | DWO No      | Type                       | Initial Result* | Action Taken** | Clearance Result |
|--|-------------|----------------------------|-----------------|----------------|------------------|
| 1 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Workroom, East Wall                      | DWO-237-001 | Faucet                     | ND              |                |                  |
| 2 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Nurse 1st Aid, East Wall                 | DWO-237-002 | Faucet                     | ND              |                |                  |
| 3 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Building Exterior, North West Wall Right | DWO-237-003 | Drinking Fountain Bubblers | <5              |                |                  |
| 4 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Building Exterior, North West Wall Left  | DWO-237-004 | Drinking Fountain Bubblers | ND              |                |                  |
| 5 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Kitchen, West Wall                       | DWO-237-005 | Faucet                     | <5              |                |                  |
| 6 2 Admin/Auditorium/Cafeteria/Kitchen - Perry_01-02<br>Parent Rm, North Wall                    | DWO-237-006 | Faucet                     | 23.81           |                |                  |
| 7 1 Kinder Rms 37-38 - Perry_01-01<br>Classroom - 37, Just inside door to the left               | DWO-237-007 | Drinking Fountain Bubblers | 2.61            |                |                  |
| 8 1 Kinder Rms 37-38 - Perry_01-01<br>Classroom - 37, Just inside door to the left               | DWO-237-008 | Drinking Fountain Bubblers | ND              |                |                  |
| 9 1 Kinder Rms 37-38 - Perry_01-01<br>Building Exterior, West Wall                               | DWO-237-009 | Drinking Fountain Bubblers | ND              |                |                  |
| 10 1 Kinder Rms 37-38 - Perry_01-01<br>Building Exterior, West Wall                              | DWO-237-010 | Drinking Fountain Bubblers | ND              |                |                  |
| 11 1 Kinder Rms 37-38 - Perry_01-01<br>Classroom - 38, Just inside the door to the right         | DWO-237-011 | Drinking Fountain Bubblers | ND              |                |                  |
| 12 1 Kinder Rms 37-38 - Perry_01-01<br>Classroom - 38, Just inside the door to the right         | DWO-237-012 | Drinking Fountain Bubblers | ND              |                |                  |
| 13 Portable B39 - Perry<br>Classroom - B39, Center Counter                                       | DWO-237-013 | Drinking Fountain Bubblers | ND              |                |                  |
| 14 5 Library - Perry_03-05<br>Workroom, East Wall  | DWO-237-014 | Faucet                     | ND              |                |                  |
| 15 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Left                   | DWO-237-015 | Drinking Fountain Bubblers | ND              |                |                  |
| 16 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Center                 | DWO-237-016 | Drinking Fountain Bubblers | ND              |                |                  |



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Perry ES

Report Type: Progress Report

Date of Report: 2/28/2019

|    | Location  | DWO No      | Type                       | Initial Result* | Action Taken** | Clearance Result |
|----|---|-------------|----------------------------|-----------------|----------------|------------------|
| 17 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Right      | DWO-237-017 | Drinking Fountain Bubblers | ND              |                |                  |
| 18 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Left       | DWO-237-018 | Drinking Fountain Bubblers | ND              |                |                  |
| 19 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Center     | DWO-237-019 | Drinking Fountain Bubblers | 2.51            |                |                  |
| 20 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, North Wall Right      | DWO-237-020 | Drinking Fountain Bubblers | 4.25            |                |                  |
| 21 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 04 Inst Sup Serv, East Wall  | DWO-237-021 | Drinking Fountain Bubblers | 2.66            |                |                  |
| 22 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 03, East Wall                | DWO-237-022 | Drinking Fountain Bubblers | ND              |                |                  |
| 23 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 02, East Wall                | DWO-237-023 | Drinking Fountain Bubblers | ND              |                |                  |
| 24 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 01, East Wall                | DWO-237-024 | Drinking Fountain Bubblers | 3.45            |                |                  |
| 25 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, South West Wall Left  | DWO-237-025 | Drinking Fountain Bubblers | 2.71            |                |                  |
| 26 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Building Exterior, South West Wall Right | DWO-237-026 | Drinking Fountain Bubblers | ND              |                |                  |
| 27 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 05, West Wall                | DWO-237-027 | Drinking Fountain Bubblers | 3.04            |                |                  |
| 28 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 06, West Wall                | DWO-237-028 | Drinking Fountain Bubblers | ND              |                |                  |
| 29 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 07, West Wall                | DWO-237-029 | Drinking Fountain Bubblers | 3.43            |                |                  |
| 30 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Classroom - 08, West Wall                | DWO-237-030 | Drinking Fountain Bubblers | 2.94            |                |                  |
| 31 | 3 Classrooms 1-9/Supply - Perry_01-03<br>Lounge, West Wall                        | DWO-237-031 | Faucet                     | 4.27            |                |                  |
| 32 | Portable B23 - Perry<br>Classroom - B23, East Wall                                | DWO-237-032 | Drinking Fountain Bubblers | 3.12            |                |                  |



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Perry ES

Report Type: Progress Report

Date of Report: 2/28/2019

|    | Location   | DWO No      | Type                      | Initial Result* | Action Taken** | Clearance Result |
|----|--|-------------|---------------------------|-----------------|----------------|------------------|
| 33 | Portable B22 - Perry Classroom - B22, East Wall                            | DWO-237-033 | Drinking Fountain Bubbler | ND              |                |                  |
| 34 | Portable B21 - Perry Classroom - B21, East Wall                            | DWO-237-034 | Drinking Fountain Bubbler | ND              |                |                  |
| 35 | Portable B20 - Perry Classroom - B20, East Wall                            | DWO-237-035 | Drinking Fountain Bubbler | ND              |                |                  |
| 36 | Portable B19 - Perry Classroom - B19, East Wall                            | DWO-237-036 | Drinking Fountain Bubbler | 4.01            |                |                  |
| 37 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North Wall Left        | DWO-237-037 | Drinking Fountain Bubbler | ND              |                |                  |
| 38 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North Wall Center      | DWO-237-038 | Drinking Fountain Bubbler | ND              |                |                  |
| 39 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North Wall Right       | DWO-237-039 | Drinking Fountain Bubbler | 5.16            |                |                  |
| 40 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North West Wall Left   | DWO-237-040 | Drinking Fountain Bubbler | 2.97            |                |                  |
| 41 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North West Wall Center | DWO-237-041 | Drinking Fountain Bubbler | ND              |                |                  |
| 42 | 4 Classrooms 10-18 - Perry_02-04 Building Exterior, North West Wall Right  | DWO-237-042 | Drinking Fountain Bubbler | ND              |                |                  |
| 43 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 13, East Wall                 | DWO-237-043 | Drinking Fountain Bubbler | 5.23            |                |                  |
| 44 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 12, East Wall                 | DWO-237-044 | Drinking Fountain Bubbler | 4.24            |                |                  |
| 45 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 11, East Wall                 | DWO-237-045 | Drinking Fountain Bubbler | 3.73            |                |                  |
| 46 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 10, East Wall                 | DWO-237-046 | Drinking Fountain Bubbler | 5.13            |                |                  |
| 47 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 14, West Wall                 | DWO-237-047 | Drinking Fountain Bubbler | 2.74            |                |                  |
| 48 | 4 Classrooms 10-18 - Perry_02-04 Classroom - 15, West Wall                 | DWO-237-048 | Faucet                    | ND              |                |                  |



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Perry ES

Report Type: Progress Report

Date of Report: 2/28/2019

| Location  | DWO No      | Type                       | Initial Result* | Action Taken** | Clearance Result |
|---|-------------|----------------------------|-----------------|----------------|------------------|
| 49 4 Classrooms 10-18 - Perry_02-04 Classroom - 16, West Wall | DWO-237-049 | Drinking Fountain Bubblers | 2.79            |                |                  |
| 50 4 Classrooms 10-18 - Perry_02-04 Classroom - 17, West Wall | DWO-237-050 | Drinking Fountain Bubblers | ND              |                |                  |

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.