



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Revere Center

Report Type: Closeout Report

Date of Report: 06/10/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	1 Risk Management/Student Records - Revere_01-01 Conference Rm, South Sink	DWO-239-001	Faucet	ND	INIT	
2	1 Risk Management/Student Records - Revere_01-01 Conference Rm, West Sink	DWO-239-002	Faucet	ND	INIT	
3	2 Food Service/Offices - Revere_02-02 Conference Rm in Gen Serv, South Sink	DWO-239-003	Faucet	ND	INIT	
4	2 Food Service/Offices - Revere_02-02 Workroom by Kitchen, North Wall	DWO-239-004	Faucet	ND	INIT	
5	2 Food Service/Offices - Revere_02-02 Kitchen, West Wall	DWO-239-005	Faucet	ND	INIT	
6	2 Food Service/Offices - Revere_02-02 Conference Rm by Office, West Wall	DWO-239-006	Faucet	ND	INIT	

\*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.