



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	100 Admin - UCHS_01-01 Nurse Office - AID1, West Wall	DWO-355-001	Faucet	2.65		
2	100 Admin - UCHS_01-01 Common Area/Hallway - HAL2, South Wall Left Bubbler	DWO-355-002	Drinking Fountain Bubbler	ND		
3	100 Admin - UCHS_01-01 Common Area/Hallway - HAL2, South Wall Right Bubbler	DWO-355-003	Drinking Fountain Bubbler	ND		
4	100 Admin - UCHS_01-01 Common Area/Hallway - HAL2, South Wall Bottle Filler	DWO-355-004	Bottle Filler	ND		
5	100 Admin - UCHS_01-01 Lounge, East Wall	DWO-355-005	Faucet	2.83		
6	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom - 201, East Wall	DWO-355-006	Faucet	5.18		
7	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom - 203, West Wall	DWO-355-007	Faucet	9.48		
8	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 206, Island Sink	DWO-355-008	Faucet	21.70		
9	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 206, West Wall	DWO-355-009	Faucet	3.56		
10	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 206, South Wall West Sink	DWO-355-010	Faucet	6.81		
11	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 206, South Wall East Sink	DWO-355-011	Faucet	4.76		
12	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 206, East Wall	DWO-355-012	Faucet	3.32		
13	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom - 205, South Wall	DWO-355-013	Faucet	4.98		
14	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Common Area/Hallway - HAL7, East Wall Left Bubbler	DWO-355-014	Drinking Fountain Bubbler	ND		
15	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Common Area/Hallway - HAL7, East Wall Right Bubbler	DWO-355-015	Drinking Fountain Bubbler	ND		
16	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Common Area/Hallway - HAL7, East Wall Bottle Filler	DWO-355-016	Bottle Filler	<5		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Left Bubbler North Exterior Of Rm 202	DWO-355-017	Drinking Fountain Bubbler	1.82		
18	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Right Bubbler North Exterior Of Rm 202	DWO-355-018	Drinking Fountain Bubbler	1.27		
19	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 211, East Wall Left Sink	DWO-355-019	Faucet	3.46		
20	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 211, East Wall Right Sink	DWO-355-020	Faucet	1.28		
21	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom - 214, North Wall	DWO-355-021	Faucet	6.79		
22	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Kitchen, East Wall Sink	DWO-355-022	Faucet	0.99		
23	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Kitchen, North Wall Prep Sink	DWO-355-023	Spray Faucet	<5		
24	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 225, East Wall	DWO-355-024	Drinking Fountain Bubbler	4.87		
25	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 226, North Wall	DWO-355-025	Drinking Fountain Bubbler	2.64		
26	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Left Bubbler By Auto Shop Lockers	DWO-355-026	Drinking Fountain Bubbler	1.10		
27	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Right Bubbler By Auto Shop Lockers	DWO-355-027	Drinking Fountain Bubbler	1.06		
28	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 231, South Wall	DWO-355-028	Drinking Fountain Bubbler	3.50		
29	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Left Bubbler South Exterior Of Rm 231	DWO-355-029	Drinking Fountain Bubbler	6.35		
30	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Building Exterior, Right Bubbler South Exterior Of Rm 231	DWO-355-030	Drinking Fountain Bubbler	2.28		
31	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom - 234, North Wall	DWO-355-031	Drinking Fountain Bubbler	3.64		
32	300 P.E. - UCHS_01-03 P.E. Gym, S.W. Corner Of Gym	DWO-355-032	Drinking Fountain Bubbler	1.02		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33	300 P.E. - UCHS_01-03 P.E. Gym, N.E. Corner Of Gym	DWO-355-033	Drinking Fountain Bubbler	1.69		
34	300 P.E. - UCHS_01-03 Building Exterior, Left Bubbler North Exterior Of P.E	DWO-355-034	Drinking Fountain Bubbler	4.93		
35	300 P.E. - UCHS_01-03 Building Exterior, Right Bubbler North Exterior Of P.E	DWO-355-035	Drinking Fountain Bubbler	2.84		
36	300 P.E. - UCHS_01-03 Building Exterior, Left Bubbler, Northeast Side Of Gym	DWO-355-036	Drinking Fountain Bubbler	2.83		
37	300 P.E. - UCHS_01-03 Building Exterior, Right Bubbler, Northeast Side Of Gym	DWO-355-037	Drinking Fountain Bubbler	1.53		
38	300 P.E. - UCHS_01-03 Locker/Boys - LKB1, Left Bubbler North Wall	DWO-355-038	Drinking Fountain Bubbler	0.54		
39	300 P.E. - UCHS_01-03 Locker/Boys - LKB1, Right Bubbler North Wall	DWO-355-039	Drinking Fountain Bubbler	0.57		
40	300 P.E. - UCHS_01-03 Restroom/Faculty Male - TFM1, West Wall In Mens	DWO-355-040	Faucet	2.40		
41	300 P.E. - UCHS_01-03 Restroom/Faculty Female - TFF1, West Wall In Womens	DWO-355-041	Faucet	2.26		
42	300 P.E. - UCHS_01-03 Locker/Girls - LKG1, Left Bubbler South Wall	DWO-355-042	Drinking Fountain Bubbler	0.94		
43	300 P.E. - UCHS_01-03 Locker/Girls - LKG1, Right Bubbler South Wall	DWO-355-043	Drinking Fountain Bubbler	0.32		
44	300 P.E. - UCHS_01-03 Building Exterior, Left Bubbler, Southeast Side Of Gym	DWO-355-044	Drinking Fountain Bubbler	0.48		
45	300 P.E. - UCHS_01-03 Building Exterior, Right Bubbler, Southeast Side Of Gym	DWO-355-045	Drinking Fountain Bubbler	1.45		
46	300 P.E. - UCHS_01-03 Foyer @ Gym, Left Bubbler West Wall	DWO-355-046	Drinking Fountain Bubbler	ND		
47	300 P.E. - UCHS_01-03 Foyer @ Gym, Right Bubbler West Wall	DWO-355-047	Drinking Fountain Bubbler	ND		
48	300 P.E. - UCHS_01-03 Foyer @ Gym, West Wall Bottle Filler	DWO-355-048	Bottle Filler	ND		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
49	300 P.E. - UCHS_01-03 Foyer @ Gym, East Wall	DWO-355-049	Drinking Fountain Bubblers	2.94		
50	300 P.E. - UCHS_01-03 Concession, East Wall	DWO-355-050	Faucet	1.87		
51	Portable Restrooms - UCHS Building Exterior, Left Bubblers South Exterior	DWO-355-051	Drinking Fountain Bubblers	0.65		
52	Portable Restrooms - UCHS Building Exterior, Right Bubblers South Exterior	DWO-355-052	Drinking Fountain Bubblers	0.54		
53	1600 Softball 1st Base Dugout - UCHS_03-22 Building Exterior, North Bubblers, By Softball Backstop	DWO-355-053	Drinking Fountain Bubblers	ND		
54	1600 Softball 1st Base Dugout - UCHS_03-22 Building Exterior, South Bubblers, By Softball Backstop	DWO-355-054	Drinking Fountain Bubblers	ND		
55	1700 Landscape Storage West - UCHS_03-24 Landscape, South Bubblers At South Side Of Storage Bldg	DWO-355-055	Drinking Fountain Bubblers	0.24		
56	1700 Landscape Storage West - UCHS_03-24 Landscape, North Bubblers At South Side Of Storage Bldg	DWO-355-056	Drinking Fountain Bubblers	ND		
57	1800 Restrooms - UCHS_03-25 Building Exterior, Left Bubblers, North Wall Of Home Side	DWO-355-057	Drinking Fountain Bubblers	0.16		
58	1800 Restrooms - UCHS_03-25 Building Exterior, Right Bubblers, North Wall Of Home Side	DWO-355-058	Drinking Fountain Bubblers	0.21		
59	1600 Baseball 1st Base Dugout - UCHS_03-20 Building Exterior, North Bubblers @ Baseball Backstop	DWO-355-059	Drinking Fountain Bubblers	0.33		
60	1600 Baseball 1st Base Dugout - UCHS_03-20 Building Exterior, South Bubblers @ Baseball Backstop	DWO-355-060	Drinking Fountain Bubblers	ND		
61	Grounds - UCHS Football Field, E Shot Put Area High Db	DWO-355-061	Drinking Fountain Bubblers	ND		
62	Grounds - UCHS Football Field, E Shot Put Area Low Db	DWO-355-062	Drinking Fountain Bubblers	ND		
63	1000 Concession/Restrooms Northwest - UCHS_03-16 Concession Stand, South Wall	DWO-355-063	Faucet	0.22		
64	1000 Concession/Restrooms Northwest - UCHS_03-16 Building Exterior, Left Bubblers, East Wall	DWO-355-064	Drinking Fountain Bubblers	0.24		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
65	1000 Concession/Restrooms Northwest - UCHS_03-16 Building Exterior, Right Bubbler, East Wall	DWO-355-065	Drinking Fountain Bubbler	0.49		
66	1100 Concession/Restrooms Southwest - UCHS_03-18 Building Exterior, Left Bubbler, East Wall	DWO-355-066	Drinking Fountain Bubbler	0.25		
67	1100 Concession/Restrooms Southwest - UCHS_03-18 Building Exterior, Right Bubbler, East Wall	DWO-355-067	Drinking Fountain Bubbler	0.17		
68	1100 Concession/Restrooms Southwest - UCHS_03-18 Concession Stand, North Wall	DWO-355-068	Faucet	0.96		
69	700 Concession/Restrooms South - UCHS_01-07 Building Exterior, North Wall	DWO-355-069	Drinking Fountain Bubbler	4.46		
70	700 Concession/Restrooms South - UCHS_01-07 Concession, West Wall	DWO-355-070	Faucet	10.90		
71	Grounds - UCHS Tennis Court, E Courts High Db	DWO-355-071	Drinking Fountain Bubbler	ND		
72	Grounds - UCHS Tennis Court, E Courts Low Db	DWO-355-072	Drinking Fountain Bubbler	0.23		
73	Grounds - UCHS Tennis Court, W Courts High Db	DWO-355-073	Drinking Fountain Bubbler	0.17		
74	Grounds - UCHS Tennis Court, W Courts Low Db	DWO-355-074	Drinking Fountain Bubbler	ND		
75	400 Classrooms/Library - UCHS_01-04 Building Exterior, Left Bubbler, East Wall By Rm 440	DWO-355-075	Drinking Fountain Bubbler	2.62		
76	400 Classrooms/Library - UCHS_01-04 Building Exterior, Right Bubbler, East Wall By Rm 440	DWO-355-076	Drinking Fountain Bubbler	1.72		
77	400 Classrooms/Library - UCHS_01-04 Science Area - 440, North Wall	DWO-355-077	Faucet	0.79		
78	400 Classrooms/Library - UCHS_01-04 Science Area - 446, North Wall	DWO-355-078	Faucet	0.47		
79	400 Classrooms/Library - UCHS_01-04 Science Area - 439, West Wall, Right Sink	DWO-355-079	Faucet	0.84		
80	400 Classrooms/Library - UCHS_01-04 Science Area - 437, South Wall	DWO-355-080	Faucet	1.28		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
81	400 Classrooms/Library - UCHS_01-04 Auxiliary - 444A, West Wall	DWO-355-081	Faucet	8.50		
82	400 Classrooms/Library - UCHS_01-04 Science Area - 444, North Wall	DWO-355-082	Faucet	0.35		
83	400 Classrooms/Library - UCHS_01-04 Auxiliary - 445A, East Wall	DWO-355-083	Faucet	12.80		
84	400 Classrooms/Library - UCHS_01-04 Science Area - 445, East Wall	DWO-355-084	Faucet	5.13		
85	400 Classrooms/Library - UCHS_01-04 Prep Rm, East Wall	DWO-355-085	Faucet	8.91		
86	400 Classrooms/Library - UCHS_01-04 Classroom - 452, East Wall	DWO-355-086	Faucet	3.50		
87	400 Classrooms/Library - UCHS_01-04 Building Exterior, Left Bubbler, South Wall By Parking Lot	DWO-355-087	Drinking Fountain Bubbler	7.60		
88	400 Classrooms/Library - UCHS_01-04 Building Exterior, Right Bubbler, South Wall By Parking	DWO-355-088	Drinking Fountain Bubbler	6.89		
89	400 Classrooms/Library - UCHS_01-04 Common Area/Hallway - HAL3, Left Bubbler South Wall,	DWO-355-089	Drinking Fountain Bubbler	<5		
90	400 Classrooms/Library - UCHS_01-04 Common Area/Hallway - HAL3, Right Bubbler South Wall,	DWO-355-090	Drinking Fountain Bubbler	0.63		
91	Food Service Kiosk - UCHS_01-13 Building Exterior, Left Bubbler, West Wall	DWO-355-091	Drinking Fountain Bubbler	2.44		
92	Food Service Kiosk - UCHS_01-13 Building Exterior, Right Bubbler, West Wall	DWO-355-092	Drinking Fountain Bubbler	<5		
93	Portable B09 - UCHS Classroom - B09, West Wall	DWO-355-093	Drinking Fountain Bubbler	1.69		
94	Portable B10 - UCHS Classroom - B10, West Wall	DWO-355-094	Drinking Fountain Bubbler	1.81		
95	Portable B08 - UCHS Classroom - B08, East Wall	DWO-355-095	Drinking Fountain Bubbler	1.13		
96	Portable B07 - UCHS Classroom - B07, East Wall	DWO-355-096	Drinking Fountain Bubbler	1.60		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: University City HS

Report Type: Progress Report

Date of Report: 05/22/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
97	Portable B06 - UCHS Classroom - B06, East Wall	DWO-355-097	Drinking Fountain Bubblers	1.54		
98	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Common Area/Hallway - HALA, South Wall Nxt To 226 Lft	DWO-355-098	Drinking Fountain Bubblers	2.53		
99	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Common Area/Hallway - HALA, South Wall Nxt To 226	DWO-355-099	Drinking Fountain Bubblers	0.94		
100	200 Auditorium/Classrooms/Kitchen - UCHS_01-02 Classroom/Non-Standard - 208, Northeast Wall	DWO-355-100	Faucet	3.54		
101	1800 Restrooms - UCHS_03-25 Building Exterior, South Side Lft	DWO-355-101	Drinking Fountain Bubblers	ND		
102	1800 Restrooms - UCHS_03-25 Building Exterior, South Side Rght	DWO-355-102	Drinking Fountain Bubblers	ND		
103	1900 Landscape Storage East - UCHS_03-26 Building Exterior, Across From Bldng 1900 Lft	DWO-355-103	Drinking Fountain Bubblers	ND		
104	1900 Landscape Storage East - UCHS_03-26 Building Exterior, Across From Bldng 1900 Rght	DWO-355-104	Drinking Fountain Bubblers	ND		

*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.