



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Vista Hill Foundation

Report Type: Proress Report

Date of Report: 04/26/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	2 Admin/Supply - Vista Hill_01-02 Workroom, south wall	DWO-129-001	Faucet	3.22		
2	6 Auditorium/Cafeteria/Kitchen/P.E. - Vista Hill_02-06 Kitchen, west wall	DWO-129-002	Faucet	<5		
3	6 Auditorium/Cafeteria/Kitchen/P.E. - Vista Hill_02-06 Counseling Rm, north wall	DWO-129-003	Faucet	<5		
4	6 Auditorium/Cafeteria/Kitchen/P.E. - Vista Hill_02-06 Staff Rm, west wall	DWO-129-004	Faucet	2.95		
5	6 Auditorium/Cafeteria/Kitchen/P.E. - Vista Hill_02-06 Building Exterior, south exterior wall	DWO-129-005	Drinking Fountain Bubbler	13.10		
6	3 Classrooms 1-5 - Vista Hill_01-03 Classroom - 01, west wall	DWO-129-007	Faucet	3.22		
7	3 Classrooms 1-5 - Vista Hill_01-03 Classroom - 02, west wall	DWO-129-008	Faucet	3.45		
8	3 Classrooms 1-5 - Vista Hill_01-03 Classroom - 03, west wall	DWO-129-009	Faucet	2.22		
9	3 Classrooms 1-5 - Vista Hill_01-03 Classroom - 05, north wall	DWO-129-010	Faucet	2.74		
10	4 Classrooms 6-9 - Vista Hill_02-04 Classroom - 06, south wall	DWO-129-011	Faucet	2.21		
11	4 Classrooms 6-9 - Vista Hill_02-04 Classroom - 07, south wall	DWO-129-012	Faucet	2.53		
12	4 Classrooms 6-9 - Vista Hill_02-04 Classroom - 08, south wall	DWO-129-013	Faucet	2.44		
13	3 Classrooms 1-5 - Vista Hill_01-03 Building Exterior, east exterior wall	DWO-129-014	Drinking Fountain Bubbler	<5		
14	4 Classrooms 6-9 - Vista Hill_02-04 Classroom - 09, north wall	DWO-129-015	Faucet	1.92		
15	4 Classrooms 6-9 - Vista Hill_02-04 Speech Dept, north wall	DWO-129-016	Faucet	3.03		
16	1 Classroom 10 - Vista Hill_01-01 Classroom - 10, west wall	DWO-129-017	Faucet	6.93		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Vista Hill Foundation

Report Type: Proress Report

Date of Report: 04/26/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	1 Classroom 10 - Vista Hill_01-01 Building Exterior, east exterior wall	DWO-129-018	Drinking Fountain Bubbler	<5		
18	Portable 11 - Vista Hill Classroom - 11, south end of room	DWO-129-019	Faucet	0.51		
19	Portable 12 - Vista Hill Classroom - 12, north end of room	DWO-129-020	Faucet	0.64		
20	Portable 13 - Vista Hill Classroom - 13, SW side of room	DWO-129-021	Faucet	0.62		
21	Portable 14 - Vista Hill Classroom - 14, SE side of room	DWO-129-022	Faucet	0.57		

*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.