



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Logan K-8

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168363	05/04/17	06:05 AM	SAMPLE 1	3710020-BBD-A	< 5	ug/L
W1168364	05/04/17	06:08 AM	SAMPLE 2	3710020-BBD-B	< 5	ug/L
W1168365	05/04/17	06:11 AM	SAMPLE 3	3710020-BBD-C	< 5	ug/L
W1168366	05/04/17	06:16 AM	SAMPLE 4	3710020-BBD-D	< 5	ug/L
W1168367	05/04/17	06:20 AM	SAMPLE 5	3710020-BBD-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Service Bldg., North wall of Kitchen, Faucet on a single compartment sink
SAMPLE 2	Service Bldg., East wall of Multipurpose room, dual bubbler fountain, right bubbler
SAMPLE 3	Service Bldg., East wall of nurse's office, Faucet on a single compartment sink
SAMPLE 4	Classroom Building, Exterior west wall of southern rr, dual bubbler fountain, right bubbler
SAMPLE 5	portable classrooms/ sport field, south of room B-10, West/lower bubbler on a concrete pedestal double fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist