



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17


San Diego Unified School District
Longfellow K-8

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171835	05/13/17	08:28 AM	SAMPLE 1	3710020-BGJ-A	< 5	ug/L
W1171836	05/13/17	08:14 AM	SAMPLE 2	3710020-BGJ-B	< 5	ug/L
W1171837	05/13/17	08:16 AM	SAMPLE 3	3710020-BGJ-C	< 5	ug/L
W1171838	05/13/17	08:22 AM	SAMPLE 4	3710020-BGJ-D	< 5	ug/L
W1171839	05/13/17	08:25 AM	SAMPLE 5	3710020-BGJ-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Lunch Court Area, East exterior wall next to lunch court, triple bubbler fountain, left bubbler
- SAMPLE 2 Kindergarten, Inside room 401 west wall, bubbler at sink
- SAMPLE 3 Classrooms 5-8 bldg, South exterior wall close to room 306, single bubbler fountain to the right of dual bubbler
- SAMPLE 4 Classrooms 11-16 bldg, East exterior wall next to girl's RR, triple bubbler fountain, right bubbler
- SAMPLE 5 Inside bungalow K-3 on south wall, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist