



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/5/17

San Diego Unified School District
Miramar Ranch Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168617	04/27/17	05:31 AM	SAMPLE 1	3710020-BCD-A	< 5	ug/L
W1168618	04/27/17	05:33 AM	SAMPLE 2	3710020-BCD-B	< 5	ug/L
W1168619	04/27/17	05:35 AM	SAMPLE 3	3710020-BCD-C	< 5	ug/L
W1168620	04/27/17	05:37 AM	SAMPLE 4	3710020-BCD-D	< 5	ug/L
W1168621	04/27/17	05:40 AM	SAMPLE 5	3710020-BCD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Lounge/lunch, south wall, triple fountain, left bubbler
- SAMPLE 2 kindergarten, north exterior wall, triple fountain, center bubbler
- SAMPLE 3 upper field bugalows, between boys/girls RR, two triple fountains, left fountain, left bubbler
- SAMPLE 4 upper kinder area, fountain near TK B-3, double fountain, left bubbler
- SAMPLE 5 second floor hallway east end, near girls RR, lower left fountain bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist