



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/26/17

San Diego Unified School District  
**Mission Bay High**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170233	05/16/17	05:58 AM	SAMPLE 1	3710020-BFE-A	< 5	ug/L
W1170234	05/16/17	06:01 AM	SAMPLE 2	3710020-BFE-B	< 5	ug/L
W1170235	05/16/17	06:06 AM	SAMPLE 3	3710020-BFE-C	< 5	ug/L
W1170236	05/16/17	06:04 AM	SAMPLE 4	3710020-BFE-D	< 5	ug/L
W1170237	05/16/17	06:10 AM	SAMPLE 5	3710020-BFE-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Kitchen, Inside kitchen, North West corner of kitchen, Right set of sinks, faucet at two compartment sink
- SAMPLE 2      Cafeteria, Outside of cafeteria north near staff café door, two dual-bubbler fountains, right fountain, right bubbler
- SAMPLE 3      Cafeteria, East wall next to tan lunch tables yellow door at right, triple bubbler fountain, left bubbler
- SAMPLE 4      200 bldg, Outside hallway Next to #223, dual bubbler fountain, left bubbler
- SAMPLE 5      200 bldg, #271 near athletic fields, dual bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist