



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17


San Diego Unified School District
Montgomery Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171727	05/13/17	05:57 AM	SAMPLE 1	3710020-BGI-A	< 5	ug/L
W1171728	05/13/17	06:05 AM	SAMPLE 2	3710020-BGI-B	< 5	ug/L
W1171729	05/13/17	06:08 AM	SAMPLE 3	3710020-BGI-C	< 5	ug/L
W1171730	05/13/17	06:00 AM	SAMPLE 4	3710020-BGI-D	< 5	ug/L
W1171731	05/13/17	06:14 AM	SAMPLE 5	3710020-BGI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria, East face of central room of kitchen, faucet above 2 compartment sink
- SAMPLE 2 Auditorium/ 600 Bldg, Exterior north wall, near restrooms, dual bubbler fountain to the right of two single fountains, right bubbler on dual fountain
- SAMPLE 3 PE building, Exterior west wall of Boys PE, two single bubbler fountains, lower right fountain
- SAMPLE 4 200 Bldg, West wall of first floor hallway, near room 214, single bubbler fountain
- SAMPLE 5 100 Bldg, West wall of second floor hallway, near room 160, single bubbler fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist