



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
John Muir Magnet

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172555	05/17/17	06:25 AM	SAMPLE 1	3710020-BHI-A	< 5	ug/L
W1172556	05/17/17	06:33 AM	SAMPLE 2	3710020-BHI-B	< 5	ug/L
W1172557	05/17/17	06:35 AM	SAMPLE 3	3710020-BHI-C	< 5	ug/L
W1172558	05/17/17	06:38 AM	SAMPLE 4	3710020-BHI-D	< 5	ug/L
W1172559	05/17/17	06:41 AM	SAMPLE 5	3710020-BHI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten/1st. Grade building, Inside K-TK classroom., double bubbler on sink, left bubbler
- SAMPLE 2 rooms 6-11 bldg, East side of building, triple bubbler fountain, left bubbler
- SAMPLE 3 Rooms 2-5 and offices bldg, East side of building, two single bubbler fountains, upper left fountain
- SAMPLE 4 Lunch court, Fountains outside lunch court east side, triple bubbler fountain, right bubbler
- SAMPLE 5 Kitchen/Auditorium, Inside kitchen east wall, faucet at single compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist