



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Muirlands Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170238	05/13/17	09:01 AM	SAMPLE 1	3710020-BFF-A	< 5	ug/L
W1170239	05/13/17	08:59 AM	SAMPLE 2	3710020-BFF-B	< 5	ug/L
W1170240	05/13/17	08:57 AM	SAMPLE 3	3710020-BFF-C	< 5	ug/L
W1170241	05/13/17	08:54 AM	SAMPLE 4	3710020-BFF-D	< 5	ug/L
W1170242	05/13/17	08:51 AM	SAMPLE 5	3710020-BFF-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Library, Outside in front of Comp Lab E across from office, dual bubbler fountain, right bubbler
- SAMPLE 2 Upper 500 bldg, In hall between boys /girls RRs and lockers, two dual bubbler fountains, left fountain, left bubbler
- SAMPLE 3 400 bldg, Outside south hall near restroom and 402-green & blue sign above, triple bubbler fountain, center bubbler
- SAMPLE 4 Cafeteria, Inside kitchen next to refrigerator, faucet above two compartment sink
- SAMPLE 5 100 bldg, Down stairs left to 100 bldg. between RRs near room 104

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist