



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17


San Diego Unified School District

Oak Park Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1164980	04/07/17	06:15 AM	SAMPLE 1	3710020-ACD-A	< 5	ug/L
W1165276	04/08/17	09:17 AM	SAMPLE 2	3710020-ACD-B	< 5	ug/L
W1164982	04/07/17	06:00 AM	SAMPLE 3	3710020-ACD-C	< 5	ug/L
W1164983	04/07/17	06:02 AM	SAMPLE 4	3710020-ACD-D	< 5	ug/L
W1164984	04/07/17	06:08 AM	SAMPLE 5	3710020-ACD-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten, Room K-1, bubbler fountain (223-1)
SAMPLE 2	Main BLDG, office hallway, bubbler outside main office (223-2)
SAMPLE 3	Cafeteria, Lunch area, triple fountain, middle bubbler (223-3)
SAMPLE 4	BLDG w/Rooms 15-24, corner near Room 15, left lower bubbler
SAMPLE 5	Bungalow, boys/girls restroom, single upper-right bubbler next to the dual fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist