



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Point Loma High

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174236	05/25/17	06:10 AM	SAMPLE 1	3710020-CAH-A	< 5	ug/L
W1174237	05/25/17	06:12 AM	SAMPLE 2	3710020-CAH-B	< 5	ug/L
W1174238	05/25/17	06:15 AM	SAMPLE 3	3710020-CAH-C	< 5	ug/L
W1174239	05/25/17	06:18 AM	SAMPLE 4	3710020-CAH-D	< 5	ug/L
W1174240	05/25/17	06:19 AM	SAMPLE 5	3710020-CAH-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Math Bldg - 100, 1st Floor, Wall mounted interior (North of Bldg), Hallway, between Men and Women RRs, two single bubbler fountains, upper right fountain
- SAMPLE 2 Classroom Bldg - 200, 1st floor, Wall mounted exterior (South of Bldg), between Men and Women RRs, facing stairs and Admin Main Office Bldg, two single bubbler fountains
- SAMPLE 3 800 Media Center, Wall mounted exterior (North of Bldg), facing Chatsworth Blvd, two single bubbler fountains, upper left fountain
- SAMPLE 4 Classroom Bldg - 300, 1st floor, Wall mounted exterior (South of Bldg), next to Boys RR, two single bubbler fountains, lower left fountain
- SAMPLE 5 1100, Weight Room, Wall mounted exterior (East of Bldg), Southwest of Football Field, next to Rollup Door, two single bubbler fountains, lower right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist