



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/19/17

San Diego Unified School District  
**Porter Elementary North**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165766	04/11/17	06:00 AM	SAMPLE 1	3710020-ADF-A	< 5	ug/L
W1165767	04/11/17	06:00 AM	SAMPLE 2	3710020-ADF-B	< 5	ug/L
W1165768	04/11/17	06:00 AM	SAMPLE 3	3710020-ADF-C	< 5	ug/L
W1165769	04/11/17	06:00 AM	SAMPLE 4	3710020-ADF-D	< 5	ug/L
W1165770	04/11/17	06:00 AM	SAMPLE 5	3710020-ADF-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Near staff restroom, behind Room N204, exterior fountain between staff restrooms, 2 fountains, left bubbler
- SAMPLE 2      Kitchen/cafeteria, prep kitchen single compartment sink, sink faucet
- SAMPLE 3      BLDG 600, behind girls/boys restrooms, two fountains, upper left bubbler
- SAMPLE 4      BLDG 400, behind restrooms, two fountains, lower right bubbler
- SAMPLE 5      BLDG 400, in Room N402, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist