



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/19/17

San Diego Unified School District
Porter Elementary South

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165294	04/11/17	06:40 AM	SAMPLE 1	3710020-ADE-A	< 5	ug/L
W1165295	04/11/17	06:45 AM	SAMPLE 2	3710020-ADE-B	< 5	ug/L
W1165296	04/11/17	06:47 AM	SAMPLE 3	3710020-ADE-C	< 5	ug/L
W1165297	04/11/17	06:30 AM	SAMPLE 4	3710020-ADE-D	< 5	ug/L
W1165298	04/11/17	06:25 AM	SAMPLE 5	3710020-ADE-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	BLDG 400, east end, right lower bubbler
SAMPLE 2	BLDG 500, Room 501, bubbler at sink
SAMPLE 3	BLDG 600 exterior, between 600 and 605, left upper bubbler
SAMPLE 4	BLDG 202, kithchen prep sink, pull down washer
SAMPLE 5	Restroom adjacent (north) of BLDG 200, exterior back, left upper bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L

Tom Burger, Associate Chemist