



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/27/17


San Diego Unified School District  
**Rodriguez Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166700	04/14/17	06:05 AM	SAMPLE 1	3710020-AEH-A	< 5	ug/L
W1166701	04/14/17	06:00 AM	SAMPLE 2	3710020-AEH-B	< 5	ug/L
W1166702	04/14/17	06:12 AM	SAMPLE 3	3710020-AEH-C	< 5	ug/L
W1166703	04/14/17	06:10 AM	SAMPLE 4	3710020-AEH-D	< 5	ug/L
W1166704	04/14/17	06:17 AM	SAMPLE 5	3710020-AEH-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1 Auditorium/Cafeteria Bldg. 800; S Wall in Kitchen; single faucet on single compartment sink
- SAMPLE 2 Auditorium/Cafeteria Bldg. 800; Exterior north wall; Lower Left-side bubbler of 3 separate single fountains
- SAMPLE 3 Bldg. 500; Exterior West wall of 1st floor girls restrooms; Left lower Bubbler of 3 separate single fountains
- SAMPLE 4 Lower Playground; NE of room 506; East/Lower Bubbler on a concrete pedestal double fountain
- SAMPLE 5 Playground; S of room 302; West/Lower Bubbler on a metallic pedestal triple fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist