

Water Quality Chemistry Services
 Lead School Testing
 Report Date: 28-Apr-2017


San Diego Unified School District
Roosevelt International Middle School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167414	4/20/2017	6:10 AM	SAMPLE 1	3710020-AGH-A	< 5	µg/L
W1167415	4/20/2017	6:15 AM	SAMPLE 2	3710020-AGH-B	< 5	µg/L
W1167416	4/20/2017	6:17 AM	SAMPLE 3	3710020-AGH-C	< 5	µg/L
W1167417	4/20/2017	6:22 AM	SAMPLE 4	3710020-AGH-D	< 5	µg/L
W1167418	4/20/2017	6:29 AM	SAMPLE 5	3710020-AGH-E	< 5	µg/L

Source **Source Description**

- SAMPLE 1 South side exterior next to B7, dual bubbler fountain, right bubbler
- SAMPLE 2 800 Building, East side exterior between bulletin board and door, triple bubbler fountain, middle bubbler
- SAMPLE 3 Lunch Court, South wall next to lunch court, two single bubbler fountains, lower right fountain
- SAMPLE 4 Physical Education Building (400 building), South exterior wall next to boy's locker room, quadruple bubbler fountain, far left bubbler
- SAMPLE 5 100 Building, West exterior wall between boys' and girls' restroom, triple bubbler fountain, left bubbler

DRL=State Mandated Detection Limit for Reporting (DLR)= 5 µg/L
 Action Level (AL) = 15 µg/L



Doug Campbell, Senior Chemist