



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Rosa Parks Elementary School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1163947	05/05/17	05:42 AM	SAMPLE 1	3710020-AAF-A	< 5	ug/L
W1163948	05/05/17	05:40 AM	SAMPLE 2	3710020-AAF-B	< 5	ug/L
W1163949	05/05/17	05:48 AM	SAMPLE 3	3710020-AAF-C	< 5	ug/L
W1163950	05/05/17	05:45 AM	SAMPLE 4	3710020-AAF-D	< 5	ug/L
W1171378	05/06/17	07:36 AM	SAMPLE 5	3710020-AAF-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria, wall mounted exterior, lunch court, near boys rest room, east wall, left bubbler (230-01)
- SAMPLE 2 Lunch court, storage area 3, west wall, right bubbler (230-02)
- SAMPLE 3 Kindergarten area @ room 1, (230-03)
- SAMPLE 4 BLDG 500, East wall under 506-509 signage, right bubbler
- SAMPLE 5 Cafeteria, food prep area, sink swing arm (230-05)

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist