



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17

San Diego Unified School District

Rowan Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165055	04/07/17	06:02 AM	SAMPLE 1	3710020-ACE-A	< 5	ug/L
W1165056	04/07/17	06:14 AM	SAMPLE 2	3710020-ACE-B	< 5	ug/L
W1165057	04/07/17	06:08 AM	SAMPLE 3	3710020-ACE-C	< 5	ug/L
W1165058	04/07/17	06:20 AM	SAMPLE 4	3710020-ACE-D	< 5	ug/L
W1165059	04/07/17	06:25 AM	SAMPLE 5	3710020-ACE-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Auditorium exterior, fountain near door, lower left bubbler.
- SAMPLE 2 BLDG 1, exterior next to Room 4, triple fountain, left bubbler
- SAMPLE 3 BLDG 2, exterior next to Room 8, triple fountain, left bubbler
- SAMPLE 4 PAL/Library, exterior, left of parent/teacher door, right fountain, single bubbler
- SAMPLE 5 BLDG 2, in Room 8, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist