



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
San Diego Cooperative Charter
Linda Vista Campus

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171645	05/09/17	06:07 AM	SAMPLE 1	3710020-BGE-A	< 5	ug/L
W1171646	05/09/17	06:10 AM	SAMPLE 2	3710020-BGE-B	6.06	ug/L
W1171647	05/09/17	06:13 AM	SAMPLE 3	3710020-BGE-C	< 5	ug/L
W1171648	05/09/17	06:17 AM	SAMPLE 4	3710020-BGE-D	< 5	ug/L
W1171649	05/09/17	06:22 AM	SAMPLE 5	3710020-BGE-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Auditorium Bldg, Interior North wall, two single bubbler fountains left of sink, upper right fountain
- SAMPLE 2 Auditorium Bldg, Exterior North wall, single bubbler fountain
- SAMPLE 3 Elementary Classrooms Bldg, Exterior East wall, adjacent to RRs, dual bubbler fountain left of triple bubbler, left bubbler on dual fountain
- SAMPLE 4 Middle School Bldg., Exterior North wall, adjacent to RRs, facing Genesee Ave, two single bubbler fountains to the right of triple bubbler, lower left single bubbler f
- SAMPLE 5 Administration Bldg, East wall inside room K-2, bubbler on sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist